Form 3160-5 (JUNE 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil (1s. Division 1625 N. French Drorm APPROVED Hobbs, N.M. 88240es: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals		 Lease Designation and Serial No. NM-84729
		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
Type of Well Oil Gas		
X Well Well Other		8. Well Name and No.
2. Name of Operator		Cuervo Federal #2
STRATA PRODUC 3. Address and Telephone No. P. O. Box 1030	TION COMPANY	9. API Well No. 30-025-31434
Roswell, New Mexico 88202-1030 505-622-1127		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Diamondtail Delaware
460' FNL & 1650' FWL		11. County or Parish, State
Section 14-23S-32E		Lea County, New Mexico
12. CHECK APPROPRIATE BOX(s) TO	D INDICATE NATURE OF NOTICE	, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X OTHER Fracture Stimulate	Oispose Water (Note: Report results of multiple completion on Well
Fracture Stimulate the Delay	ware "A-1" and "A-2" zones. (7088-	7151')
O DOLL / Is	TU. /	No. 127
2. POH w/rods, pump and tubir	ng. TIH w/pakcer and RBP.	
 POH w/rods, pump and tubir POH w/tubing and packer. F 		APPROVED
,,,	Prep to frac down tubing.	APPROVED
3. POH w/tubing and packer. F	Prep to frac down tubing.	APPROVED
3. POH w/tubing and packer. F	Prep to frac down tubing.	APPROVED WWW 9
3. POH w/tubing and packer. F	Prep to frac down tubing.	(A) C
3. POH w/tubing and packer. F	Prep to frac down tubing.	APPROVED VOV. 0 CARY GOURLEY FET FOLERWISHORNER
3. POH w/tubing and packer. F4. Swab and flow to recover loan	Prep to frac down tubing. ad and test.	CARY GOURLEY
3. POH w/tubing and packer. F 4. Swab and flow to recover load 14. I hereby certify that the foregoing is true and correct 14. I hereby certify that the foregoing is true and correct.	Prep to frac down tubing. ad and test.	CARY GOURLEY FETT DIEUW E-GINTER
3. POH w/tubing and packer. F 4. Swab and flow to recover load 14. I hereby certify that the foregoing is true and correct Signed Humman.	Prep to frac down tubing. ad and test.	CARY GOURLEY
3. POH w/tubing and packer. F 4. Swab and flow to recover load 14. I hereby certify that the foregoing is true and correct 14. I hereby certify that the foregoing is true and correct 15. I hereby certify that the foregoing is true and correct 16. I hereby certify that the foregoing is true and correct 17. I hereby certify that the foregoing is true and correct 18. I hereby certify that the foregoing is true and correct 19. I hereby certify that the foregoing is true and correct 19. I hereby certify that the foregoing is true and correct 19. I hereby certify that the foregoing is true and correct 19. I hereby certify that the foregoing is true and correct 19. I hereby certify that the foregoing is true and correct 19. I hereby certify that the foregoing is true and correct 19. I hereby certify that the foregoing is true and correct 19. I hereby certify that the foregoing is true and correct 19. I hereby certify that the foregoing the correct certification that the foregoing the correct certification that the correct certification the certification that the correct certification that the certif	Prep to frac down tubing. ad and test.	CARY GOURLEY FETT DUFUM HACINTER

BOSTONIA L- NON 1008 CENERALD