

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
Harvard Petroleum Corporation

3. Address and Telephone No.  
P.O. Box 936, Roswell, NM 88202-0936 (505)623-1581

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

810' FSL & 1830' FEL  
Sec. 29 T23S-R32E N.M.P.M.

5. Lease Designation and Serial No.

NM-0559539

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

James Federal #1

9. API Well No.

30-025-31515

10. Field and Pool, or Exploratory Area

West Triste/Delaware

11. County or Parish, State

Lea, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other Drilling & Completion  
Status
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

2-21-92 WOC, weld on 8 5/8" X 5 1/2" Larkin "92" wellhead. NU BOP and test to 2000#. Start drilling cmt plug at 5:30 a.m.  
2-22 thru 2-25 Drilling  
2-26-92 TD well at 4848' Run 4844' 5 1/2" 17# K-55 csg. Cmt w/ 100 sks Class "C" w/ 2% CaCl, bump plug @ 2:15 p.m.  
2-28 thru 3-1 MI RU cable tool unit, bail down well and start drilling on cmt shoe.  
3-2 thru 3-10 Drilling w/ cable tool to 4940' TD  
3-11-92 RU Schlumberger, run Gamma Ray and Compensated Neutron Log.  
3-12 thru 3-28 Evaluate logs and test well.  
3-29-92 Drill 4 more feet, TD 4944'  
3-29 thru 5-20 Evaluate and test well  
5-21-92 RD cable tool unit, Decide to convert well over to a SWD.

RECEIVED  
JUL 8 11 25 AM '92  
21982  
SJS

14. I hereby certify that the foregoing is true and correct

Signed Jeff Harvard (Jeff Harvard) Title Vice President

Date 7/7/92

(This space for Federal or State office use)

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

Date \_\_\_\_\_