

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
NM-85940

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Urraca Federal #2

9. API Well No.

30-025-31625

10. Field and Pool, or Exploratory Area

Diamondtail Delaware

11. County or Parish, State

Lea County, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Strata Production Company

3. Address and Telephone No.

P.O. Box 1030, Roswell, NM 88202-1030 (505)622-1127

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

560' FSL & 660' FWL
Section 11-23S-32E

12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☒ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log forms.)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Strata Production Company hereby proposes to workover and recompleate the referenced well in the following manner:

1. ND wellhead. POH with rods and pump. Install BOP. POH with tubing.
2. RU. PU and TIH with packer and RBP. Set RBP at 7080'. Swab down. POH with packer.
3. Perf Delaware "AA" zone from 7045' to 7047'. Swab and/or flow to test and evaluate.
4. Release packer. Latch on to RBP. POH and LD packer and RBP.
5. RIH with tubing and production installation. RIH with rods and pump. Place on production.

14. I hereby certify that the foregoing is true and correct

Signed Carol J. Garcia

Title Production Records Manager

Date 11/14/94

(This space for Federal or State office use)

Approved by (ORIG. SGD.) JOE G. LARA
Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date 12/12/94

RECEIVED

SEP 14 1991
UCC
OFF