Form 3160-5 (July 1989) (Formerly 9-331) DE SUNDRY (Do not use this form	Hodil'ied Porm No <u>MOG()-3160-4</u> 5. LEASE DESIGNATION <u>NM-62224</u> 6. IF INDIAN, ALLOTTEN	AND SERIAL NO.			
Use "APPLICATION FOR PERMIT-" for such proposals.)			7. UNIT AGREEMENT NAME		
NAME OF OPERATOR Strata Production Company		3a. Area Code 6 Phone No. 505-622-1127	8. FARM OF LEASE NAME Aracanga Federal		
P. O. Box 1030, Roswell, New Mexico 88202-1030 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements." See also space 17 below.) At surface 1650' FSL & 1650' FEL			9. WELL RO. #2 10. FIELD AND POOL, OR WILDCAT Wildcat Delaware 11. SBC., T., R., M., OR RLE. AND SURVEY OR ARMA		
14. PERNIT NO. 30-025-31651	15. BLEVATIONS (Show whether DI 3684 [†] GR	15. RLEVATIONS (Show whether DP, RT, GR, etc.) 3684 t CD		Section 9-23S-32E 12. COOPTI OR PARISE 13. STATE	
16. Ch	eck Appropriate Box To Indicate N	Nature of Notice, Report, or (I Lea Other Data	NM	
TRET WATER BHUT-OFF PRACTURE TREAT RHUOT OR ACIDIZE REPAIR WELL (Other)	OF INTENTION TO : FULL OR ALTER CASING MULTIPLE CONFLETE ABANDON* CHANGE PLANE CHANGE PLANE STRD OPERATIONS: (Clearly state all pertinen directionally drilled, give subsurface locations)	WATER SHUT-OFF FRACTI'RE TREATMENT SHOUTING OR ACIDIZING (Other) RID CASING (Note: Report result	of multiple completion of	a Well	

8/30/92 Drilled to 4555'. Ran 59 joints of 8 5/8" 32# J55 casing and 48 joints of 8 5/8" 24# J55 casing. Cemented at 4555' with 110 sacks Halliburton Lite, 10# per sack salt, 1/4# per sack Flocele, and 200 sacks Class "C" with 2% calcium chloride. Circulated 150 sacks to pit. Waiting on cement. Pressure test BOP to 500#. OK.

	A	
	Í	9 1992
18. I hereby cyclify that the foregoing p true and correct		
(This space for Federal or State office use)	TITLE Production Supervisor	DATE8/31/92
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE

*See Instructions on Reverse Side