

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**

Form C-103  
Revised 1-1-89

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) <b>30-025-31752</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT
8. Well No. 200
9. Pool name or Wildcat ARROWHEAD / GB
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3430' GE

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator CHEVRON U.S.A. INC.
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	4. Well Location Unit Letter <u>J</u> : <u>1780</u> Feet From The <u>SOUTH</u> Line and <u>1880</u> Feet From The <u>EAST</u> Line Section <u>7</u> Township <u>22S</u> Range <u>37E</u> NMPM <u>LEA</u> County
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3430' GE	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTER CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐  
CASING TEST AND CMT JOB ☐  
OTHER: DRILLING SUMMARY ☒

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including  
estimated date of starting any proposed work) SEE RULE 1103.

MIRU ROD-RIC # 4 ON 10-26-92.  
SPUD 12.25" HOLE, DRILL AND SURVEY TO 1161'.  
RUN 8 5/8" CASING TO 1161', PUMP 750 SX. OF CEMENT AND CIRCULATE 250 SX. TO SURFACE.  
WAIT ON CEMENT FOR 12.5 HOURS, DRILL OUT FLOAT AND CMT TO SHOE, TEST CSG TO 1000#-OK.  
DRILL AND SURVEY 7 7/8" HOLE TO 3885'.  
RUN 5.5" CASING TO 3885', PUMP 730 SX. CEMENT AND CIRCULATE 300 SX. TO SURFACE.  
INSTALL WELLHEAD AND TEST.  
RELEASE RIG ON 11-1-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE TECH. ASSISTANT DATE: 11-5-92

TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO. (915)687-7812

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT I SUPERVISOR DATE NOV 09 '92  
CONDITIONS OF APPROVAL, IF ANY: