

**DISTRICT I**

P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**

P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-32334</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>V-2795</b>
7. Lease Name or Unit Agreement Name <b>Snakeweed 31 State</b>
8. Well No. <b>1</b>
9. Pool name or Wildcat <b>Wildcat (Delaware)</b>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator <b>Parker &amp; Parsley Development L.P./Pioneer Natural Resources USA, Inc.</b>	
3. Address of Operator <b>P.O. Box 3178, Midland, TX 79702</b>	
4. Well Location Unit Letter <b>H</b> : <b>660</b> Feet From The <b>East</b> Line and <b>1980</b> Feet From The <b>North</b> Line Section <b>31</b> Township <b>23S</b> Range <b>33E</b> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-13-97 Set CIBP @ 5050' - Spot 25 sxs cement on top  
2-14-97 Spot 52 sxs @ 4317'-3827' tagged - cover casing cut  
2-17-97 Spot 40 sxs @ 3350'-3208' tagged - pulled 3300' of 5 1/2" casing  
2-18-97 Spot 40 sxs @ 1260'-1130' tagged  
2-18-97 Spot 40 sxs @ 120' to surface

INSTALL DRY HOLE MARKER  
CIRCULATE HOLE WITH 10# MUD  
JERRY SEXTON WITH THE OCD WITNESSED THE PLUGGING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cindy Whiddon TITLE Sr. Production Accountant DATE 8/3/2000  
TYPE OR PRINT NAME: Cindy Whiddon TELEPHONE NO. 915/571-3125

(This space for State Use)

APPROVED BY Terry W. Hill TITLE Director DATE 8/3/2000  
CONDITIONS OF APPROVAL, IF ANY:

GWW