orm 3160-5 lune 1990)	DEPART	NITED STATES ENT OF THE INTERIOR F LAND MANAGEMENT			FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals						5. Lease Designation and Serial No. LC-032104 6. If Indian, Alottee or Tribe Name		
SUBMIT IN TRIPLICATE						7. If Unit or CA, Agreement Designation		
					8. Well Name and Number BLINEBRY, A.H. FEDERAL NCT-1			
2. Name of Operator	· · · · · · · · · · · · · · · · · · ·	RATION & PRODUC	TION INC.			45		
. Address and Telephone	P.O. BOX 730, H	OBBS, NM 88240		397-0426	9. API Well No.	30 025 32673		
 Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit Letter <u>M</u>: <u>330</u> Feet From The <u>SOUTH</u> Line and <u>990</u> Feet From The 					10. Field and Pool, Exploratory Area Tubb Oil and Gas			
NEST Line	Section 20	Township22-S	Range	. 38-E	11. County or Par	ish, State LEA , NM		
2. (Check Appropria	te Box(s) To Ind	icate Natur	e of Notice. R	eport. or Oth	er Data	·	
TYPE OF SUBN					YPE OF ACTION			
Notice of Inter Subsequent R	eport		Abandonment Recompletion Plugging Back Casing Repair Altering Casing OTHER:			Change of Plans New Construction Non-Routine Frac Water Shut-Off Conversion to Inje Dispose Water e: Report results of multiple	cturing	
Objective: Texaco inte At a later date, Texaco	Completed Operations (C ve subsurface locations an nds to plug-back the cu will attempt to administr roduction equipment. In	d measured and true vert rrent Drinkard-Abo con atively downhole comm	ical depths for all internation and perfo	markers and zones pe prate uphole into the	g estimated date of s rtinent to this work,) Tubb Oil and Gas	*. s interval	d work. If well is	
2. TIH with RBP and s	et @ 6800' (Drinkard - /	Abo perforations @ 68	52'-6982').					
3. Perforate Tubb Oil a	and Gas zone on interva	l 6096'-6258' with 2 jsp	of.			ج -د	2	
4. TIH with packer and	i set @ 6000'.						and Barry a start of St Barry (set Barry a	
5. Acid treat with 4000	g 15% NEFE HCL + ba	llsealers.					trianana teasara teasara	
6. Fracture treat well w	/ith 47500g gel +193000	# 20/40 sand.					and a second sec	
7. Flow well back.								
8. Release packer and	ТОН.							
9. TIH with production	equipment and place or	n pump.						
10. Test production. A	3160-4 (completion rep	oort) + a sundry 3160-5	i (subsequent wo	orkover report) will b	e submitted at the	conclusion of this	project.	
14. I hereby certify that the sereo								
SIGNATURE	MO C	TITLE	Engineeri	ng Assistant		DATE	1/12/96	
TYPE OR PRINT NAME	Darre				· _ · · · · ·			
(This space for Federal or State of APPROVED BY	RIG SCD.) JO	E.G. LARA	PET	ROLEUN E	GINEER		6/96	
CONDITIONS OF APPR Title 18 U.S.C. Section 1001 representations as to any ma	, makes it a crime for any pers	on knowingly and willfully to	make to any departm	ent or agency of the Unit	ed States any false, fict	itious or fraudulent stat	tements or	

1

э

