

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT --" for such proposals

5. Lease Designation and Serial No.

NM 18848

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number

SDE '31' FEDERAL

8

9. API Well No.

30-025-32867

10. Field and Pool, Exploratory Area

SAND DUNES; BONE SPRING, SOUTH

11. County or Parish, State

LEA, NM

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address and Telephone No. P.O. BOX 730, HOBBS, NM 88240 397-0418

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter K : 1980 Feet From The SOUTH Line and 1980 Feet From The

WEST Line Section 31 Township 23-S Range 32-E

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ OTHER:
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☒ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PRIOR TO THIS WORKOVER TO RECOMPLETE TO THE SAND DUNES; BONE SPRINGS, SOUTH POOL, THIS WELL PRODUCED FROM THE TRISTE CRAW; DELAWARE, WEST POOL. THE INTENT TO PERFORM THE RECOMPLETION WAS SUBMITTED ON 12/13/95.

10/19/95 - 10/26/95

1. MIRU. TOH W/ PRODUCTION EQUIPMENT. SET CIBP @ 7350'. SET PKR ABOVE CIBP & TSTD TO 3000#, OK. RESET PKR @ 7061'. SQZD TRISTE DRAW; DELAWARE, WEST PERFS FROM 7246'-7280' W/ 100 SXS CLASS H CMT, REVD OUT 33 SXS CMT. RELEASED & TOH W/ PKR & WS.
2. TAGGED CMT @ 7068', CLEANED OUT CMT TO CIBP @ 7350', TSTD SQZD PERFS TO 1000#, BLED OFF 200# IN 2 MIN. TOH W/ WS.
3. SET PKR @ 7061', SQZD PERFS AGAIN FROM 7246'-7280' W/ 100 SXS CLASS H CMT, REVD OUT 9 BBLS CMT.
4. ATTEMPTED TO UNSET PKR, PKR STUCK, HAD TO MILL OUT & FISH PKR. DRILLED OUT CMT FROM 7061'-7245'. TSTD CSG TO 1000#, OK.
5. DRILLED OUT CEMENT & CIBP @ 7350'. CLEANED OUT TO 9800' (PBTD).
6. PERFORATED W/ 2 JSPF IN SAND DUNES; BONE SPRING, SOUTH POOL FROM 8560'-8614' (55' NET, 110 HLES).
7. SET TREATING PKR @ 7400'. LOAD BACKSIDE & TSTD PKR TO 500#. OK. ND BOP, NU TREE. ACIDIZED PERFS 8560'-8614' W/ 3000 GAL 15% NEFE HCL W/ BALLSEALERS. RELEASED PKR, LOWERED PKR TO WIPE OFF PERFS, RESET PKR @ 7400'.
8. FRACTURE TREATED PERFS 8560'-8614' W/ 74,500 GALLONS 35# XLG 2% KCL & 261,301 16/30 RESIN COATED SAND. SCREENED OUT, LEFT SAND IN TBG. USED COILED TBG UNIT, TIH TO PKR @ 7400', CIRCD OUT SAND. CLEANED OUT SAND TO 9000'. RELEASED & TOH W/ PKR & WORKSTRING.
9. SET PRODUCTION PKR @ 8428', TSTD PKR TO 800#, OK. SWABBED TSTD WELL. LEFT WELL FLOWING TO BATTERY.

OPT 12/4/95: FLOWING 125 BOPD, 19 BWPD, 212 MCFD ON 20/64 CHOKE; FLOWING TUBING PRESSURE = 200#

14. I hereby certify that the foregoing is true and correct

SIGNATURE Monte C. Duncan TITLE Engr Asst

DATE 12/18/95

TYPE OR PRINT NAME Monte C. Duncan

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.