

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER  
2. Name of Operator: TEXACO EXPLORATION & PRODUCTION INC.  
3. Address and Telephone No: 205 E. Bender, HOBBS, NM 88240 397-0405  
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Unit Letter N : 660 Feet From The SOUTH Line and 1980 Feet From The  
WEST Line Section 31 Township 23-S Range 32-E

5. Lease Designation and Serial No. NM-18848

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number  
SDE 31 FEDERAL

14

9. API Well No. 30-025-32915-32916

10. Field and Pool, Exploratory Area  
TRISTE DRAW, DELAWARE, WEST

11. County or Parish, State  
LEA, NM

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ OTHER: CLEAN OUT, INSTL PMP  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

5-20-99: MIRU. NDWH. INSTL BOP. KILL WELL W/70 BBLS 2% KCL. TOH W/231 JTS 2 7/8" TBG.  
5-21-99: TIH W/BIT, TBG, & BAILER. TAG FILL @ 5600'. C/O TO PBTD @ 9684'. PULL TBG & STOP BIT @ 3147'.  
5-24-99: TIH W/RBP & PKR & SN & TBG. SET RBP @ 8656'. PULL PKR TO 8498'. ATTEMPT TO SET @ 8498'. ATTEMPT TO SET PKR SEVERAL TIMES UP TO 7363'. SET PKR @ 7363'.  
5-25-99: ACIDIZE PROP LOCK BONE SPRINGS PERFS 8550-8610 W/1000 GALS 15% NEFE HCL. PUMP 546 GALS PROP LOCK, FLUSH & OVER FLUSH W/88 BBLS 2% KCL.  
5-26-99: RU SWAB. FL @ 5000'. END FL @ 6500'. REL PKR & TIH TO RBP @ 8656'. LATCH & REL RBP. PULL UP TO 7369' & RE-SET. PULL UP & SET PKR @ 7235'. TEST RBP TO 500#-OK. PULL PKR TO 7107' & SET. TEST BACKSIDE TO 500#-OK.  
5-27-99: PRESS CSG TO 500#-OK. ACIDIZE & PROP LOCK BRUSHY CANYON PERFS 7176-7190'. PUMP 1000 GALS 15% NEFE HCL. FLUSH W/41 BBLS 2% KCL WTR. ALL PUMPED ON VAC.  
5-28-99: REL PKR. TIH TO RBP @ 7369'. LATCH & REL RBP. TIH W/RET TOOL. TAG PLUG @ 1200'. LATCH ONTO PLUG.  
5-29-99: TIH W/PROD TBG & TAG @ 8614'. TAG SAND @ 8587'. C/O FR 8587-8776'. RAN BIT TO PBTD @ 9684'.  
6-01-99: TIH W/BIT & TAG FILL @ 9669'. C/O TO 9684'. TIH W/PROD TBG. OPMA @ 8740. SN @ 8716. TAC @ 7140. NDBOP. NUWH.  
6-02-99: TIH W/GAS ANCHOR, PMP & b RDS. HANG WELL ON. LOAD & TEST TO 500 PSI-OK.  
6-03-99: LONG STROKE & ATTEMPT TO GET PUMP TO PUMP - NO SUCCESS.  
6-04-99: RUN PMP & RDS.  
6-07-99: RIG DOWN.  
8-03-99: ON 24 HR OPT. PUMPED 22 BO, 114 BW, & 86 MCF.

FINAL REPORT

14. I hereby certify that the foregoing is true and correct

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 8/15/99  
TYPE OR PRINT NAME J. Denise Leake

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: TITLE DATE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.