

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Co.
P 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM-35164
2. Name of Operator TOCO L. L. C.	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P. O.; BOX 888, HOBBS, NM 88241 (505) 393-2727	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2310' FNL & 720' FEL, SEC 10, T23S, R34E	8. Well Name and No. NEWKUMET FEDERAL #1
	9. API Well No. 30-025-32937
	10. Field and Pool, or Exploratory Area ANTELOPE RIDGE (BRUSHY CANYON)
	11. County or Parish, State LEA CO., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other SWAB & FRAC
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

07/24/97, MIRU, Pull pump & rods, tag bottom of tbg @ 7890'. Set CIBP @ 7495'. Perf 6991'-93', 6994'-98', 7001'-03'.
07/25/97 RIH & swab. Swbd dry in 3 runs. Acid w/1500 gal. 7½% NEFE. swab back approx 75 bbls of load. Avg. trtg press. 1400#, ISIP 302#.
07/26/97 14 swab runs to dry up well w/200'/hr fluid entry.
07/27/97 2 Swab runs, no oil. Set CIBP @ 6980', Perf 6735'-38' & 6758'-62', acid 1000 gal 7½ NEFE & flush acid to perfs w/39 bbl. prod wtr made 11 swab runs.
07/28/97 Swbd dry in 7 runs. waited 1 hr, made swab run, no recovery.
07/29/97 Swbd dry in 4 runs, approx. 200' fluid entry, could not recover w/swab.
07/30/97 Swbd dry in 4 runs, no fluid entry.
07/31/97 Rig up to frac. Frac screened outw/37,000# through perfs, w/6000# sd in tbg. Reversed well & cleaned out tbg.
08/01/97 Tag sd @ 6840'. POH w/tbg. Set anchor, RIH w/rods.
08/03/97 Rods parted, Shut down, waiting on pulling unit

14. I hereby certify that the foregoing is true and correct

Signed <u>Boye Heard</u>	Manager Oil Reports & Gas Services, Inc.
(This space for Federal or State office use)	Title <u>Agent for TOCO L. L. C.</u> Date <u>08/07/97</u>
Approved by _____	Title _____ Date _____
Conditions of approval, if any:	