

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.")		WELL API NO. 30 025 33296
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.		6. State Oil / Gas Lease No. 15340
3. Address of Operator 205 E. Bender, HOBBS, NM 88240		7. Lease Name or Unit Agreement Name ANDERSON, T.
4. Well Location Unit Letter <u>I</u> : <u>1650'</u> Feet From The <u>SOUTH</u> Line and <u>430'</u> Feet From The <u>EAST</u> Line Section <u>8</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY		8. Well No. 5
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3543' GL</u>		9. Pool Name or Wildcat MONUMENT BLINEBRY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☒ ADD PAY & ACIDIZE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-09-97: MIRU. Shut down.
 5-12-97: POH RODS & PUMP. INSTALL BOP. POH.
 5-13-97: TAG PBTD 5833'. LAY DOWN TBG. RU SCHLUMBERGER & TIH W/GUN & PERF BLINEBRY CSG 2 JSPF.5600-5717 (40-.47" HOLES).TOH RD
 5-14-97: TIH W/RBP & PKR. TESTED TO 5000#.SET RBP @ 5650'AND TEST TO 1100#OK. PULL UP & SET PKR. @ 5552'. RU DOWELL AND ACIDIZE BLINEBRY PERFS. 5580-5612 W/ 2000 GALS 15% NEFE HCL AND 45 7/8 BALLS. MAX PRESS=4500#,MIN PRESS=0,AVG=1500,AIR=5BPM,ISIP=VACUUM. UNSET PKR & LATCH ONTO RBP @ 5650, MOVE & RESET RBP @5794'. PULL UP & SET PKR @ 5647'. BY DOWELL ACIDIZE BLINEBRY PERFS. 5674-5717 W/ 2000 GALS 15% NEFE HCL & 51-7/8 BALLS.' SURGE OFF BALLS. MAX PRESS=4869#,MIN PRESS=2648', AVG=3000#,AIR=4.1BPM. ISIP=1250#,6MSIP=VACUUM. RELEASE PKR. RESET 5552' SDFN.
 5-15-97: SITP=850#.FLOWED TO TANK 30 MINS.RU SWAB. STARTING FLUID LEVEL 3000' SWABBED 4 HRS RECOVERED 35 BBLS. 80% OIL.FLUID LEVEL STAYING @ 3000'. RD SWAB. RELEASE PKR & LOWER TOOLS & LATCH ONTO RBP & TOH W/ TBG,PKR & RBP. RAN PRODUCTION TBG & SET @5759'. ND BOP. NU WELL HEAD.
 5-16-97: TIH W/PUMP & RODS. HUNG ON RDMO. PUMPING & TESTING
 5-17-97 THRU 6-25-97: PUMPING & TESTING
 6-24-97: On 24 hour POTENTIAL TEST ending 10 am. Pumped 50 Bbls Oil, 11 Bbls Water, & 112 MCF Gas. FINAL REPORT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paula S. Ives TITLE Engineering Assistant DATE 10/1/97
 TYPE OR PRINT NAME Paula S. Ives Telephone No. 397-0432

(This space for State Use) ORIGINAL SIGNED BY DAVID WILLIAMS
 APPROVED BY DISTRICT I SUPERVISOR TITLE DATE OCT 10 1997
 CONDITIONS OF APPROVAL, IF ANY: