

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-33794
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	A. B. Baker
8. Well No.	6
9. Pool name or Wildcat	Blinebry Oil & Gas (Pro Gas)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Collins & Ware, Inc.	
3. Address of Operator 508 West Wall, Suite 1200, Midland, Texas 79701	
4. Well Location Unit Letter I : 2135 Feet From The South Line and 829 Feet From The East Line Section 10 Township 22S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3385' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate and treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Please see attachment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Administrator DATE 5/19/98

TYPE OR PRINT NAME Dianne Sumrall

TELEPHONE NO. (915) 687-3435

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 26 1998

CONDITIONS OF APPROVAL, IF ANY:

2A Wants Abn do

ATTACHMENT TO FORM C-103
COLLINS & WARE, INC.
BAKER #6

- 04/28/98** Release packer and pull out of hole. Run in hole with CIBP and set at 6450'. Test CIBP to 500# with no leak off. Perf Blinebry from 5402 - 5422 and 5482 - 5502 with 1 JSPF, 42 holes. Go in hole and set RBP at 5592 and packer at 5306. Begin swabbing.
- 04/29/98** Set packer at 5463. AT perfs 5482 - 5502 with 1400 gals 15% Ferchek acid with 35 ball sealers. Reset RBP at 5470 and packer at 5306. AT perfs 5402 - 5422 with 1400 gals 15% Ferchek and 35 ball sealers. Achieved ball out. Reset RBP at 5592.
- 04/30/98** Frac perfs 5402 - 5502 with 67,900 gals Delta Frac and 160,000# 20/40 Ottawa sand.
- 05/02/98** Bail sand to top of RBP at 5592. Release RBP and and pull out of hole with RBP and bailer. Wash down casing with 50 bbls of 2% KCL. Pick up and run 5 1/2" Perma Latch packer and set at 5339' with 10 points compression. Begin swabbing.
- 05/04/98** Turn over to production.