

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-025-33794
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	A. B. Baker
8. Well No.	6
9. Pool name or Wildcat	Wantz AB0

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Collins & Ware, Inc.	
3. Address of Operator 508 West Wall, Suite 1200, Midland, Texas 79701	
4. Well Location Unit Letter <u>I</u> : <u>2135</u> Feet From The <u>South</u> Line and <u>829</u> Feet From The <u>East</u> Line Section <u>10</u> Township <u>22S</u> Range <u>37E</u> NMPM 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3385' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate & stimulate <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/22/97 Dropped "F" plug. Load tubing and test plug to 2500 psi. Release on-off tool and P00H with 1 joint tubing. Dump 1 sx sand. RIH with 4" casing gun. Tag sand at 6955'. Perforate 6900' - 6920' with 2 SPF (40 perfs). Spot 50 gals 15% NEFE acid from 6920 - 6870. Acidized with 1950 gals 15% NEFE acid.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Supervisor DATE 4/8/97

TYPE OR PRINT NAME Dianne Sumrall

(This space for State Use)

TELEPHONE NO. (915) 687-3435

APPROVED BY Chris Williams TITLE District Supervisor DATE 6/2/97

CONDITIONS OF APPROVAL, IF ANY

FOR RECORD ONLY

