

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025- 06874 33870
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Brunson-Argo
Well No. 20
Pool name or Wildcat Wantz Abo

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
Name of Operator Titan Resoureces I, Inc.	
Address of Operator 500 West Texas, Suite 500, Midland, Texas 79701	
Well Location Unit Letter <u>A</u> <u>467</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>09</u> Township <u>22S</u> Range <u>37E</u> NMPM Lea County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3417' GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Perf Upper ABO & Acidize ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/16/98 MIRU, TOH rods & pump
4/17/98 TIH RBP & pkr, set RBP @ 6690', pkr @ 6675', test RBP 3000 psi, Load hole w/2% KCL, spot 200 gal 15% NEFE, Perf Upper ABO (6662'-6666') 9 total hole, 2 SPF, TIH pkr, profile nipple, on/off tool & tbg, tested to 8000 psi, set pkr @ 6385'.
4/18/98 Acidize ABO (6662'-6666') 5000 gals 50Q CO2, flushed CO2, flowed back.
4/19/98 Flow & swab well.
4/21/98 Set blanking plug, unlatch from pkr, latch on pkr, release pkr, TOH LD tbg.
4/22/98 Pump down backside, well pressured up, TOH blanking plug, pump 20 bbls 2% KCL down tbg, LD workstring.
4/23/98 Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley Melton TITLE Engineering Tech DATE 07-27-98
TYPE OR PRINT NAME Shirley Melton TELEPHONE NO. (915)498-8604

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: