

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. (Cons. Division
P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM-88164

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Parsley ARA Federal #1

9. API Well No.

30-025-33863

10. Field and Pool, or Exploratory Area

Wildcat Delaware

11. County or Parish, State

Lea Co., NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

YATES PETROLEUM CORPORATION (505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

760' FSL & 990' FEL of Section 26-T23S-R32E (Unit P, SESE)

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work)*

Propose to temporarily abandon Bone Springs perforations 8971-10075' and recomplete to Delaware as follows:

1. TOOH with pump and rods. Nipple up BOP. TOOH with tubing.
2. TIH with RBP and set at 8900' to temporarily abandon perforations 8971-10075' (Bone Springs). Test RBP to 2000 psi.
3. Perforate 8521-8550' (Delaware), acidize and frac as necessary for production.
4. Swab/flow test.
5. Place well into production.

NOTE: If decision is made to commingle Bone Springs and Delaware, application will be made to OCD-Santa Fe, OCD-Hobbs and BLM-Roswell.

RECEIVED
1997 MAY 28 P 9:46
BUREAU OF LAND MGMT.
ROS WELL OFFICE

APPROVED
(ORIG. SGD) DAVID R. GLASS

14. I hereby certify that the foregoing is true and correct

Signed

[Signature]

Title

Operations Technician

Date May 27, 1997

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date