Submit 3 Copies To Appropriate District State of New Mexico Form C-103 energy, Minerals and Natural Resources Revised March 25, 1999 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 District II 30 - 025 - 34497**OIL CONSERVATION DIVISION** 811 South First, Artesia, NM 87210 5. Indicate Type of Lease District III 2040 South Pacheco STATE 1000 Rio Brazos Rd., Aztec, NM 87410 FEE Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH SARAH JOHNSTON PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other HOME-STAKE OIL & GAS COMPANY 8. Well No. Name of Operator 15 E. 5<sup>th</sup> Street Address of Operator Suite 2800 Tulsa, OK 74103 9. Pool name or Wildcat Wantz-Abo and Drinkard Well Location feet from the SOUTH line and 2040 feet from the **EAST** Unit Letter O: 800 Section Township 22S Range 37E **NMPM** County LEA 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3346' GR 3364' KB 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ALTERING CASING ☐ CHANGE PLANS COMMENCE DRILLING OPNS. **PLUG AND** TEMPORARILY ABANDON **ABANDONMENT** MULTIPLE CASING TEST AND PULL OR ALTER CASING COMPLETION **CEMENT JOB** X OTHER: Recomplete in Abo & Drinkard Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. See a Hacked proposal details. I hereby certify that the information above is true and complete to the best of my knowledge and belief. **SIGNATURE** TITLE Production Engineer DATE 12/14/00 Telephone No. (918) 583-0178 Type or print name Larry Tarwater (This space for State use) TITLE APPPROVED BY Conditions of approval, if any:

## HOME-STAKE OIL & GAS COMPANY

## **SARAH JOHNSTON #1**

API NO. 30-025-34497

UL "O" Section 22 – T22S – R37E Lea County

## ATTACHMENT TO FORM C-103: SUNDRY NOTICE FOR PROPOSED ABO/DRINKARD RECOMPLETION

Note: Work to begin as soon as well service unit becomes available.

- Day 1: Rig up wireline unit. Set CIBP 7050'. Cap with 2 sacks cement via dump bailer.
- Day 2: Perforate Abo with 3-1/8" casing gun, 2 SPF, as follows: 6645', 6649', 6651', 6657', 6762', 6764', 6772', 6785', 6793', 6796'. Rig down wireline unit.
- Day 3-4: Run 2-7/8" tubing and packer. Set packer @ 6560'. Swab well down. Acidize Abo perfs with 2000 gals 15% HCl acid. Swab back load. Swab test Abo.
- Day 5: Pull tubing and packer. Rig up wireline unit and set RBP on wireline at 6600'. Perforate Drinkard with 3-1/8" casing gun, 2 SPF, as follows: 6314', 6346', 6364', 6368', 6391', 6396', 6398', 6405', 6420', 6422', 6436', 6438', 6441', 6469', 6478', 6489'. Run tubing and packer. Set packer at 6250'. Swab well down.
- Day 6: Acidize Drinkard with 3000 gals 15% HCl acid. Swab well back to test.
- Day 7: Frac Drinkard with procedure to be determined.
- Day 8-10: Swab to recover frac load. Swab test Drinkard.
- Day 11: Prepare for down-hole commingling:
  Pull RBP. Re-run tubing, including mud anchor, seating nipple and tubing anchor.
  Run pump and rods and put well on production.

12-14-00