Submit 3 Copies To Appropriate District				
• • • •	State of New Mexico	WINDO Form C-103		
Office Energy, Minerals and Natural Resources		Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.		
District II 811 South First, Artesia, NM 88210 OIL C	CONSERVATION DIVISION	30025-34810 5. Indicate Type of Lease		
District III	2040 South Pacheco			
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.		
<u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505	,	0. State Off & Oas Lease No.		
SUNDRY NOTICES AND R	EPORTS ON WELLS	7. Lease Name or Unit Agreement Name:		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRIL	L OR TO DEEPEN OR PLUG BACK TO A	TOMCAT '16' STATE		
DIFFERENT RESERVOIR. USE "APPLICATION FOR P.	ERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.) 1. Type of Well:				
Oil Well Gas Well Othe	r			
2. Name of Operator		7. Well No.		
CONCHO RESOURCES INC.		4 A Wildoot		
3. Address of Operator 110 W. LOUISIANA STE 410: MIDLAND TX 79701 8. Pool name or Wildcat SAND DUNES BONE SPRING				
110 W. EOCIDITATE TO, MEDICAL ST.				
4. Well Location				
Unit Letter E: 1650 feet fr	om the <u>NORTH</u> line and <u>460</u>	feet from the <u>WEST</u> line		
T	ownship 23S Range 32E	NMPM LEA County		
	ownship 23S Range 32E tion (Show whether DR, RKB, RT, GR, e			
3651' GR	uon (bhow whether bit, intb, itt, oit, o			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION	TO: SUE	SSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK 🔲 PLUG AND	ABANDON REMEDIAL WOR	RK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON	PLANS COMMENCE DE	RILLING OPNS. PLUG AND		
		ABANDONMENT		
PULL OR ALTER CASING MULTIPLE		AND		
COMPLET	ION CEMENT 30B	L		
OTHER:	OTHER: Comple	· 1		
12. Describe proposed or completed operations	s. (Clearly state all pertinent details, and	give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
		or recompilation.		
or recompilation.		ota)		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @	4012'. Perf @ 8445-75' w/2 SPF (50 sh	ots). 3C sand		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I	oots). RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'.	nots). RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE.	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE.	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE.	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE.	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes).	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/3	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/3	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE 11/15/00 Frac well w/ 794 bbls 71264# sand.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/3	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/3	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE 11/15/00 Frac well w/ 794 bbls 71264# sand. 11/16/00 TIH w/ tbg, pump & rods. EOT @ 69	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/3	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE 11/15/00 Frac well w/ 794 bbls 71264# sand. 11/16/00 TIH w/ tbg, pump & rods. EOT @ 69	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/3	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE 11/15/00 Frac well w/ 794 bbls 71264# sand. 11/16/00 TIH w/ tbg, pump & rods. EOT @ 69 11/20/00 IP: 17 BO, 97 BW, 42 MCF.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/30 SEFE. Swab well.	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE 11/15/00 Frac well w/ 794 bbls 71264# sand. 11/16/00 TIH w/ tbg, pump & rods. EOT @ 69 11/20/00 IP: 17 BO, 97 BW, 42 MCF.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/30 SEFE. Swab well.	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE 11/15/00 Frac well w/ 794 bbls 71264# sand. 11/16/00 TIH w/ tbg, pump & rods. EOT @ 69 11/20/00 IP: 17 BO, 97 BW, 42 MCF.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/30 SEFE. Swab well.	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE 11/15/00 Frac well w/ 794 bbls 71264# sand. 11/16/00 TIH w/ tbg, pump & rods. EOT @ 69 11/20/00 IP: 17 BO, 97 BW, 42 MCF.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/30 SEFE. Swab well.	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE 11/15/00 Frac well w/ 794 bbls 71264# sand. 11/16/00 TIH w/ tbg, pump & rods. EOT @ 69 11/20/00 IP: 17 BO, 97 BW, 42 MCF.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/30 SEFE. Swab well.	RC sand.		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE 11/15/00 Frac well w/ 794 bbls 71264# sand. 11/16/00 TIH w/ tbg, pump & rods. EOT @ 69 11/20/00 IP: 17 BO, 97 BW, 42 MCF.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 99' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/3 EFE. Swab well. 240'. TITLE Production	edge and belief. n Analyst DATE 9-15-00 Telephone No. 915-683-7443		
or recompilation. 09/19/00 Ran CBL from 8927-6500'. TOC @ 09/20/00 Frac @ 8445-70 w/ 34,100 gals Vikin 09/21/00 Perf @ 7392-7409' w/ 2 SPF (35 shot 09/22/00 Set pkr @ 7306'. Acidize @ 7392-74 09/27/00 Frac 7392-7409 w/ 26000 gals Viking 09/28/00 TIH w/ prod tbg, pump & rods. 10/2/00 to 10/21/00 testing & evaluating well. 11/09/00 Move RBP to 7200'. 11/10/00 Perf @ 6962-75 w/ 2 SPF (27 holes). 11/11/00 Acidize @ 6962-75 w/ 1000 7.5% NE 11/15/00 Frac well w/ 794 bbls 71264# sand. 11/16/00 TIH w/ tbg, pump & rods. EOT @ 69 11/20/00 IP: 17 BO, 97 BW, 42 MCF.	4012'. Perf @ 8445-75' w/2 SPF (50 sh g 30# gel, 60920# 16/30, 12120# 16/30 I s). Set RBP @ 7600'. 09' w/ 2000 gals 7.5% NEFE. 30 gel, 60460# 16/30 sand, 12280# 16/30 SPE. SPE. Swab well. 040'. TITLE Productio	edge and belief. n Analyst DATE 9-15-00		