			N.M. OII 🗂	ons. Division PPROVED
(June 199	,		1625 N. rre	Pinch Devoies: March 31, 1993
	DEPARTMENT OF BUREAU OF LAND		Hobbs NM	506240 nation and Serial No.
	DUREAU OF LAND	WANAGEMENI	10000, 1414	5000000 Million and Serial No. NM-62223
	SUNDRY NOTICES AN	D REPORTS ON WE	LLS	6. If Indian, Allottee or Tribe Name
Do ne	ot use this form for proposals to drill		-	
		PERMIT" for such propos		
	SUBMIT			7. If Unit or CA, Agreement Designation
1. Type of W				
Oil Well	Gas Well Other			8. Weil Name and No.
2. Name of C	perator			SHARBRO FEDERAL #7
	INDUSTRIES, INC.			9. API Well No.
3. Adress and Telephone No.				30-025-35144
P.O. BOX 840, ARTESIA, NM 88211-0840 (505)748-4274 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				10. Field and Pool Or Exploratory Area SAND DUNES DELAWARE EAS
	FSL & 660' FWL		F	SAND DUNES DELAWARE EAS
				· · · · · · · · · · · · · · · · · · ·
40	-T23S-R32E (UNIT L) NMPM			LEA, NM
			TYPE OF ACT	
	Notice of Intent	Abandonment	Ę	Change of Plans
	X Subsequent Report	Recompletion	Ļ	New Construction
		Plugging Back	Ľ	Non-Routine Fracturing
	Final Abandonment Notice		Ĺ	Water Shut-off
		Altering Casing	1	I Conversion to Exection
			L LONGSTRING CSG	Conversion to Injection Dispose Water
		X Other INTERMEDIATE		Dispose Water (Note: Report results ofmultiple completion on Well Completion of Recompletion Report and Log form.)
directionally	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure	Other INTERMEDIATE	ates, including estimated dat and zones pertinent to this w	Dispose Water (Note: Report results ofmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is fork.)*
directionally	Proposed or Completed Operations (Clearly state	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC	ates, including estimated dat and zones pertinent to this w	Dispose Water (Note: Report results ofmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is fork.)*
directionally 9/9/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC of SXS.	ates, including estimated dat and zones pertinent to this w @ 4466' CMT W/160	Dispose Water (Note: Report results stmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY
13. Describe P directionally 9/9/00 9/16/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-5	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC of SXS.	ates, including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results .sfmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C".
directionally 9/9/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-5	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC of SXS.	ates, including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results stmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY
directionally 9/9/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-5	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC of SXS.	ates, including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results .sfmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C".
directionally 9/9/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-5	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC of SXS.	ates, Including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results .sfmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C".
directionally 9/9/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-5	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC of SXS.	ates, Including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results ofmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD
directionally 9/9/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-5	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC of SXS.	ates, Including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results ofmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD
directionally 9/9/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-5	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC of SXS.	ates, Including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results ofmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD
directionally 9/9/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-5	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC of SXS.	ates, Including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results ofmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD
directionally 9/9/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-5	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC of SXS.	ates, including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD OGT 1 3 2000
directionally 9/9/00 9/16/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-S TD 8510' RAN 203-JTS 5-1/2" (1	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC (5XS. 7#) W/FS @ 8510' & FC @ 8	ates, including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results ofmultiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD
directionally 9/9/00 9/16/00 2/16/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-S TD 8510' RAN 203-JTS 5-1/2" (1 TD 8510' RAN 203-JTS 5-1/2" (1	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC (5XS. 7#) W/FS @ 8510' & FC @ 8	ates, including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD OGT 1 3 2000
directionally 9/9/00 9/16/00 2/16/00	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-S TD 8510' RAN 203-JTS 5-1/2" (1 TD 8510' RAN 203-JTS 5-1/2" (1 RETURN: 7000 0520 0017 1084 2469 certify that the foregoing is true and	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC 5XS. 7#) W/FS @ 8510' & FC @ 8	ates, including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD OGT 1 3 2000
directionally 9/9/00 9/16/00 9/16/00 <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u>	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-S TD 8510' RAN 203-JTS 5-1/2" (1 Note: 10, 10, 10, 10, 10, 10, 10, 10, 10, 10,	all pertinentdetails, and give pertinent d d and true vertical depts for all markers 5/8" W/GS @ 4502' AND FC (5XS. 7#) W/FS @ 8510' & FC @ 8 7#) W/FS @ 8510' & FC @ 8	ates, including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S	Dispose Water (Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is ork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD OGT I 3 2000 G. SGD.) GARY GOURLEY
directionally 9/9/00 9/16/00 9/16/00 <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u> <u>9/16/00</u>	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-S TD 8510' RAN 203-JTS 5-1/2" (1 TD 8510' RAN 203-JTS 5-1/2" (1 RETURN: 7000 0520 0017 1084 2469 certify that the foregoing is true and	Correct	ates, Including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S ACCE	Dispose Water (Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD OGT I 3 2000 G. SGD.) GARY GOURLEY ER Date 10/6/00
directionally 9/9/00 9/16/00 9/10 9/10 9/10 9/10 9/10 9/10 9/10 9	Proposed or Completed Operations (Clearly state y drilled, give subsurface locations and measure TD 4503' RAN 110-JTS (32#) 8-5 200-SXS "C" + 2%. CIRC. 282-S TD 8510' RAN 203-JTS 5-1/2" (1 Note: 10, 10, 10, 10, 10, 10, 10, 10, 10, 10,	Correct	ates, Including estimated dat and zones pertinent to this w @ 4466' CMT W/160 474'. CMT W/200-S ACCE	Dispose Water (Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form.) e of starting any proposed work. If well is rork.)* 0-SXS LITE FOLLOWED BY XS LITE + 500-SXS "C". PTED FOR RECORD OGT I 3 2000 G. SGD.) GARY GOURLEY ER Date 10/6/00

* See Instruction on Reverse Side

5