Submit 3 Cop. s To Appropriate District Office	Ditte of 110 visit in				Form C-103 Revised March 25, 1999	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 87240  Energy, Minerals and Natural Resources				WELL API		
District II 811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION			5. Indicate	Type of Lease Fed		
District III 2040 South Pacheco 1000 Rio Brazos Rd., Aztec, NM 87410			1	STATE   FEE		
District IV Santa Fe, NM 87505			<b></b>	Oil & Gas Lease No.		
2040 South Pacheco, Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other NJECTION					7. Lease Name or Unti Agreement Name THOMPSON 19 FEDERAL	
2. Name of Operator QUAY VALLEY, INC				8. Well No	0. 2	
3. Address of Operator P. O. BOX 10280 MIDLAND TX 79702-7280					9. Pool name or Wildcat MASON DELAWARE, NORTH	
4. Well Location				MASONI	DELAWARE, NORTH	
Unit Letter F : 1980 feet from the NORTH line and 1980 feet from the WEST line						
Section 19	Township26-	·S Ra	inge 32-E	NMPM	CountyLEA	
5001.5.1	10. Elevation (Show w					
11 Charle A	3,195' DF	licata No	tura of Nation	Donort or C	)ther Data	
NOTICE OF IN PERFORM REMEDIAL WORK				<b>IBSEQUEN</b>	T REPORT OF:  ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE	RILLING OPNS	S. PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST CEMENT JOBS		ABANDONWENT	
OTHER:			OTHER:			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.  Surface casing: 8-5/8" 24# @ 1,014' cmt'd w/350 sx, circulated Production csg: 5-1/2" 14# csg @ 4,320' cmt'd w/350 sx, TOC @ 3,080' by temperature survey  4" flushjoint liner 4,052-4,300' Perforations: 4,303-4,307' (Delaware) 2-3/8" IPC tubing to 4,034' w/1-1/2" tubing to 4" Guiberson packer @ 4,292'  1. POOH w/injection equipment. 2. RIH w/tbg-set CIBP and sct @ 4,000'. Circulate mud and pump 105 x C cmt on top of CIBP. 3. Cut and pull 5-1/2" casing based on steeth measurements, estimated 1,500'. 4. Pump 40 sx C cmt across csg stub. TAG. 50/NH 50 00T 10 64 10 964 6. Pump 30 sx C cmt 50' below surface casing shoe. TAG. 10 64 10 964 6. Pump 30 sx C cmt @ 700'. 7. Pump 10 sx C cmt 50' to surface.  THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BECINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE	(Wann	TITLE_	PRESIDENT		DATE 11/28/2000	
Type or print nameSTELLA SWA	ANSON, CPL		· · · · · · · · · · · · · · · · · · ·		Telephone No. (915)687-4220	
(This space for State use)  APPROVED BY Conditions of approval, if any:	Whink	_TITLE_	1 41		DATE NOW	

5 L S