

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Injection Well Temp. Shut-in	7. UNIT AGREEMENT NAME North El Mar Unit
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME North El Mar Unit
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 6
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit B	10. FIELD AND POOL, OR WILDCAT El Mar Delaware
14. PERMIT NO. 660' FNL & 2005' FEL 30-025-08280	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25-265-32E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU on 12/14/85, Tag @ 4657', CO 37' of fill
- ② Set RBP @ 4597', isolated leaks from 835'-900'; Ran open ended to 942'; Spot 50 sxs class "C" cmt w/ 2% CaCl₂ plug.
- ③ Tag cmt @ 451'. Drill out to 950' and fell thru. Clean out to 1060'; Test csq to 60 psi for 20 min., held OK. Circ. sand off RBP. Retested csq and wouldn't hold. Isolated leaks from 838'-898'. Spot 2sxs on RBP.
- ④ Pmp'd 50 sxs class "C" w/ 2% CaCl₂. Sqz to 1500 psi. Repressure test csq to 500 psi, bled down to 300 psi in 30 min. Tag cmt @ 671', drill out to 881'.
- ⑤ GIH w/ bit & scraper, Set pkr @ 929'; Reset pkr @ 470'. Mix & pump 50 sxs class "C" Thix-o-tropic cmt w/ 2% CaCl₂.
- ⑥ Tag cmt @ 562', DO to 728' circ. Drill cmt - rom 740'-870' circ. hole
- ⑦ Circ. sand of RBP & POOH. Clean out from 4627'-4670'.
- ⑧ Set pkr @ 4592' Test csq to 510 psi for 30 min w/ no leak off. Rig down on 1-6-86

19. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

DATE

1-6-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

JAN 7 1986

*See Instructions on Reverse Side