

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. <u>LC-068777</u>
2. NAME OF OPERATOR <u>CONOCO INC.</u>	6. INDIAN ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, N.M. 88240</u>	7. UNIT AGREEMENT NAME <u>North El Mar</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface: <u>Unit A</u>	8. FARM OR LEASE NAME <u>North EL Mar Unit</u>
14. PERMIT NO. <u>660' FNL & 330' FEL</u>	9. WELL NO. <u>45</u>
15. ELEVATIONS (Show whether OF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT <u>El Mar Delaware</u>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 36-26S-32E</u>
	12. COUNTY OR PARISH 13. STATE <u>Lea NM</u>

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLAN ☐	(Other) ☐	(Other) ☐
(Other) <u>temporary abandon</u> ☒		(Other) ☐	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markets and zones pertinent to this work.)

NOTE: Report results of multiple completion on Well Completion or Recompletion Report and log form.

- ① MIRU. POOH w/ production equip. Make bit & scraper run to perfs.
- ② GIH w/ CIBP & pkr to $\pm 4540'$. Set CIBP @ $\pm 4540'$. Test CIBP to 1000 psi. Test backside to 600 psi.
- ③ Rel pkr & POOH. Circ. hole full of 10.0 ppg brine. Rig down.



18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>12-17-86</u>
(This space for Federal or State office use)		
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u>12-18-86</u>
CONDITIONS OF APPROVAL, IF ANY:		

*See instructions on Reverse Side

[Illegible handwritten text]

RECEIVED
DEC 22 1966
HON. CHIEF