

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

SEP 15 1965

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-6622
7. Unit Agreement Name -
8. Farm or Lease Name State 36
9. Well No. 4
10. Field and Pool, or Wildcat El Mar - Delaware
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Kern County Land Company
3. Address of Operator 418 First State Bank Bldg., Midland, Texas 79704
4. Location of Well UNIT LETTER E , 542 FEET FROM THE South LINE AND 336 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 26S RANGE 32E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3101' RT

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Kill well with lease crude.
2. Trip tubing for new packer.
3. Frac with 1000 gal refined oil pad followed by 3000 gal refined oil and 4500# 10-20 m. sand.
4. Trip tubing. Run pump and rods.
5. Install pumping unit and place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>P. J. Easton</i></u>	TITLE <u>District Engineer</u>	DATE <u>9-14-65</u>
APPROVED BY <u></u>	TITLE <u></u>	DATE <u></u>

CONDITIONS OF APPROVAL, IF ANY: