HOPBS OFFICE CO. Form 9-331 a. (Feb. 1951) Budget Bureau No. 42-R358.4 Approval expires 12 (1-60) (SUBMIT IN TRIPLICATE) Land Office Las Cruces UNITED STATES Lease No. IC 068378 DEPARTMENT OF THE INTERIOR Unit PD GEOLOGICAL SURVEY RECEIVED

JUN2 3 1959 NOTICES AND REPORTS ON WELLS S. GEOLOGICAL DURVEY NOTICE OF INTENTION TO DRILL HOBBS, NEW MEXICO NOTICE OF INTENTION TO CHANGE PLANS SUBSEQUENT REPORT OF WATER SHUT-OFF

NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL

SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY

INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA!

June 22. is located 660 ft. from line and 660 ft. from line of sec. 13 Wildcat (Field) (County or Subdivision)

The elevation of the derrick floor above sea level is 3346 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sixes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

Set 329° 8 5/8" casing. Set at 342°, cement circulated, 10 sks at top of 10 sks at 350°

15 sks at \$90° Top Rustler at 870°

2# sks at 1240°, Base Rustler at 1220°

25 sks at 5100°, Top Delaware Sand at 5210° Set 4° Marker 4° above surface.

Clean location.

Mariner, celled 7/807 stilling 7-20-39 for OK FED

told Wort we would impost wontern when month or so

Company HILL & MBEKER

Address 519 Midland Savings & Loan Bldg.

Midland, Texas

Title Production Clerk

API 30-025-08414