Salyan y or approval

Land Office Las Cruces

Lease No. Lo 068378

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

OCT 5 YOUR WOLLENGING IS

SUNDRY NOTICES AND REPORTS ON WELLS. Galon HOBBS, NEW IN

NOTICE OF INTENTION TO DRILL

NOTICE OF INTENTION TO CHANGE PLANS

NOTICE OF INTENTION TO TEST WATER SHUT-OFF

NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL

NOTICE OF INTENTION TO SHOOT OR ACIDIZE

NOTICE OF INTENTION TO PULL OR ALTER CASING

NOTICE OF INTENTION TO ABANDON WELL

SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT. SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT. NOTICE, OR OTHER DATA)

September 18, 1959

Well No.

Form 8-381 a (Feb. 1951)

is located 660 ft. from |N | line and 1980 ft. from |W | line of sec. 25

NE/4. NW/4. Sec. 25 26S

N.M.P.M.

Wildcat

County or Subdivision

The elevation of the derrick floor above sea level is 3358 ft.

DETAILS OF WORK

(State names of and expected depths to which tive sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

Set 337: 8 5/8" casing, set at 346: - cement circualted.

Cement Flugs:

10 sks at top of surface & ground lavel

16 sks at 35 \*\*

If sks at 840: - top of Rustler at 820:

25 sks at 1194 - Base of Rustler at 11751

25 sks at 522 1 - Top of Delaware Sard at 52351

Hole full of mud laden material. Set 4" marker 4: above surface.

Glean Location.

Toward Al - Ho mank

a plan of white must receive approval in writing by the Geological surgey before operations may be commenced.

Called Out the Book Filed Secon Matheway Asset he wheely saft They to

Company HILL & MEEKER Jestily is therety when ready for interesting the

Address 519 Midland Savings

Midland, Texas

Title Production Clerk

SPO 862"4

Afferme & med