

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ <u>shut-in</u>	5. LEASE DESIGNATION AND SERIAL NO. <u>LC-030139(A)</u>
2. NAME OF OPERATOR <u>CONOCO INC.</u>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, N.M. 88240</u>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>Unit E</u>	8. FARM OR LEASE NAME <u>Lynn A</u>
14. PERMIT NO. <u>30-025-09433</u>	9. WELL NO. <u>3</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>2310' FNL & 330' FWL</u>	10. FIELD AND POOL, OR WILDCAT <u>Jalmat Yates 7 Rurs</u>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 27-235-36E</u>
	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

NOTE: Report results of multiple completion on Well Completion or Recompletion Report and log form.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- ① MIRU. scrape csg to 3300'. Set cmt ret @ 3250'. Sqz perfs w/ 25 sxs class "C" cmt. String out of ret & spot 40 sxs cmt on top.
- ② Circ. hole full of 12.0 ppg mud. Spot 145' cmt plug from 1405'-1550' w/ 15 sxs class "C" (across top of salt section)
- ③ Perf @ 415' w/ 2 JS PF. Establish circ. down 5 1/2", thru 9 5/8" annulus. Pump 150 sxs class "C" w/ 2% CaCl₂.
- ④ Cut off well head & install P&A marker. Rig down.
- ⑤ A proposed P&A sketch is attached.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Administrative Supervisor DATE 1-20-87

(This space for Federal or State office use)

APPROVED BY Orig. Sgd. Charles C. Dutton TITLE Assistant Secretary DATE 1-26-87

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side