

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5. Indicate Type of Lease	
State ☐	Fee ☒
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSALS.

1. Indicate Type of Well: OIL ☐ GAS ☐ OTHER ☒ WIW

2. Name of Operator: ARCO Oil and Gas Company
Division of Atlantic Richfield Company

3. Address of Operator:
P. O. Box 1710, Hobbs, New Mexico 88240

4. Location of Well:

UNIT LETTER M 330 FEET FROM THE South LINE AND 330 FEET FROM
THE West LINE. SECTION 34 TOWNSHIP 23S RANGE 36E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3406' DF

7. Unit Agreement Name

8. Farm or Lease Name
B. Davis

9. Well No.
1

10. Field and Pool, or Wildcat
Jalmat Yates 7R

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging procedure approved verbally w/Mr. Jerry Sexton on 10/28/82.

1. RU, POH w/injection assy. RIH w/CR. Set retr @ 2885'. Squeeze cmt perfs 3110-3508' w/200 sx Cl C cmt, spot 35' cmt on top of retr.
2. Spot heavy gel mud, perf 4 holes 1400-1401'. Set pkr @ 1350', establish circ w/BW. POH w/pkr.
3. Set cmt retr @ 1380' & squeeze cmt perfs @ 1400-1401' w/200 sx Cl C cmt, close BH valve & squeeze cmt in salt section. Spot 35' cmt on top of retr. Spot salt gel brine wtr from TOC to 60' FS.
4. Spot 10 sx cmt (60' plug) to surface. Cut off well head & install regulation dry hole marker. Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Robert E. Bell</u>	TITLE <u>Drlg. Engr.</u>	DATE <u>11/30/82</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPR.		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

DEC 2 1982

RECEIVED
DEC 1 1982
O.C.D.
HOBBS OFFICE