

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Atlantic Richfield Company | 8. Name of Lease Name J. P. Combest WN |
| 3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240 | 9. Well No. 2 |
| 4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 35 TOWNSHIP 23S RANGE 36E N.M.P.M. | 10. Field and Pool, or Wildcat Langlie Mattix 7Rivers On |
| 11. Elevation (Show whether DF, RT, GR, etc.) 3550' GR | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|--|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | LM 7RQ zone only | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |
| OTHER <input type="checkbox"/> | | OTHER <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and list pertinent dates, including estimated date of completion of work) SEE RULE 1103.

TD 3630', PBD 3618'. Present perfs are Langlie Mattix 7Rivers On 3536-3610'. Propose to P&A LM7RQ zone and recompleate in Jalmat Gas zone. Procedures to P&A LM7RQ zone are as follows:
1. Rig up, kill well, install BOP & POH w/completion assy.
2. Set cmt retr @ 3500'.
3. Squeeze LM perfs 3536-3610' w/150 sx Cl C cont'g 4% gel.

Plans to recompleate to Jalmat Gas reported separately on Form C-101.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Dist. Dirg. Supt. DATE 2/2/77

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: