

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3-NMOCD-HOBBS
1-R. J. STARRAK-TULSA
1-A. B. CARY-MIDLAND

1-PJB, ENGR.
1-FILE

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR NOTICES TO ABANDON OR TO RETURN TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR PERMIT TO RE-ENTER OR TO RE-LEASE FOR SUCH PURPOSES.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Water Supply Well
2. Name of Operator
Getty Oil Company
3. Address of Operator
P. O. Box 730, Hobbs, NM 88240
4. Location of Well
UNIT LETTER E 1260 FEET FROM THE South LINE AND 1130 FEET FROM
THE West LINE, SECTION 3 TOWNSHIP 24-S RANGE 36-E NMPM.

7. Unit Agreement Name
8. Form or Lease Name
Eugene Coats
9. Well No.
3
10. Field and Pool, or Wildcat
Jalmar
12. County
Lea

13. Elevation (Show whether DF, RT, CR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER Acidize ☒
PLUG AND ABANDON ☐
CHANGE PLANS ☐
SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. Rig up pulling unit.
2. Pull submersible pump.
3. Pick up 3 1/2" tubing and packer.
4. Set packer at $\pm$ 3400'.
5. Acidize as per Dresser Titan's recommendations.
6. Pull tubing and packer.
7. Run submersible equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Area Superintendent DATE 5-15-80
DATE R. Crockett

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: