NUMBER OF COPIE	S RECEI	VES		
DIS	TRIBUTI	он		
SANTA FE		I		
FILE		L		1
U.S.G.5.				
LAND OFFICE				
TRANSPORTER	OIL		1	į
	GAS	1		
PRORATION OFFI	CE	<u> </u>		
		t	1	

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

S STOP 14 17 05 11 164

GAS GATION OFFICE	MISCELLANEOUS	NOTICES ' ' G G G G G G	64
RATOR	strict Office, Oil Conservation Con-	imission, before the work specified is	in. A copy will be by the Commission
artica to the schael on which An	toe given the approval, with any modificat	nmission, before the work specified is to see tions considered advisable, or the rejection l work should not begin until approval is o	btained. See addi-
agent, of the plan submitted. The nal instructions in the Rules and	Regulations of the Commission.		
nai instructions in the state and	Indicate Nature of Notice by Ci	hecking Below	
	T	Notice of Intention	
TICE OF INTENTION	Notice of Intention to Temporarily Abandon Well	TO DRILL DEEPER	
CHANGE PLANS	I	Notice of Intention	
TICE OF INTENTION PLUG WELL	Notice of Intention to Plug Back	TO SET LINER	
PLUG WELL	Notice of Intention	Notice of Intention	
OTIGE OF INTENTION	TO ACIDIZE	то Ѕност (Nitro)	
SQUEEZE	Notice of Intention	Notice of Intention	
OTICE OF INTENTION OF GUN PERFORATE	(Other) Clean out &	(OTHER)	
	test for Water Suppl		30 304
IL CONSERVATION COMMIS		Mexico Septembe	r 10, 1964
ANTA FE, NEW MEXICO	(Place)	_	
entlemen:			
Following is a Notice of Inter	tion to do certain work as described below	at the	нан
Shally O	Il Company Eugene Coat	BWell No4	n(Unit)
(Company	or Operator)	50°	Poo
, - ·	01 C - 26 P	Ranglia Matti	
SE 1/4 SE 1/4 of Se	3, T24-S, R. 36-E	Langlia Matti	
(40.2010.02.00		Langlie Matti	
(40.4010.04.00.00.00.00.00.00.00.00.00.00.00.00	County.		
Lea		D PLAN OF WORK	
Les	County.	D PLAN OF WORK	
Lea	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RI	D PLAN OF WORK ULES AND REGULATIONS)	
Lea	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RI	D PLAN OF WORK ULES AND REGULATIONS)	
l. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
1. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
l. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RI g up pulling unit. nt plug at 3464, and clean of	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
1. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
l. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE O	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
1. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE O	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
1. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE O	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
1. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE O	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
1. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE O	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
1. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE O	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
1. Move in and ri	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE O	D PLAN OF WORK ules and regulations) out to total depth of 3544.	
1. Move in and ri 2. Drill out ceme 3. Run Reda Pump. 4. Test for Water	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RI g up pulling unit. nt plug at 3464' and clean of Supply well for approximate	D PLAN OF WORK ULES AND REGULATIONS) Out to total depth of 3544. Bly 60 days. Skelly Oil Compa	an y
1. Move in and ri 2. Drill out ceme 3. Run Reda Pump. 4. Test for Water	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RISE OF PROPOSE IN THE RISE OF THE RISE O	D PLAN OF WORK ULES AND REGULATIONS) Out to total depth of 3544. Bly 60 days. Skelly Oil Compa	an y
1. Move in and ri 2. Drill out ceme 3. Run Reda Pump. 4. Test for Water	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RIGHT of pulling unit. Int plug at 3464 and clean of Supply well for approximate.	D PLAN OF WORK ULES AND REGULATIONS) out to total depth of 3544.	an y
1. Move in and ri 2. Drill out ceme 3. Run Reda Pump. 4. Test for Water	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RI g up pulling unit. nt plug at 3464' and clean of Supply well for approximate By	Skelly Oil Compagnets of Supplemental Compagnets of Supplemental Compagnets of Supplemental Compagnets of Supplemental Compagnets of Compagnet	any Lab
1. Move in and ri 2. Drill out ceme 3. Run Reda Pump. 4. Test for Water Approved	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RI g up pulling unit. nt plug at 3464' and clean of Supply well for approximate By	Skelly Oil Company of the Company of	any Lab
1. Move in and ri 2. Drill out ceme 3. Run Reda Pump. 4. Test for Water Approved Except as follows:	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RI g up pulling unit. nt plug at 3464' and clean of Supply well for approximate By	Skelly Oil Companies	any well to:
1. Move in and ri 2. Drill out ceme 3. Run Reda Pump. 4. Test for Water Approved Except as follows: Approved OHL CONSERVATION COMM	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RI g up pulling unit. nt plug at 3464! and clean of Supply well for approximate By Posit	Skelly Oil Companies Dist. Supt. Skelly Oil Companies Send Communications regarding Skelly Oil Companies Skelly Oil Companies Send Communications regarding	well to:
1. Move in and ri 2. Drill out ceme 3. Run Reda Pump. 4. Test for Water Approved Except as follows: Approved OHL CONSERVATION COMM	FULL DETAILS OF PROPOSE FOLLOW INSTRUCTIONS IN THE RI g up pulling unit. nt plug at 3464! and clean of Supply well for approximate By Posit	Skelly Oil Companies	well to: