

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-09510
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Texaco Exploration & Production, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator P. O. Box 3109, Midland, TX 7902		7. Lease Name or Unit Agreement Name: Eugene Coats
4. Well Location Unit Letter <u>K</u> : 1980 feet from the <u>South</u> line and 1980 feet from the <u>West</u> line Section <u>3</u> Township <u>24-S</u> Range <u>36-E</u> NMPM Lea County		8. Well No. 6
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Jalmat Tansill, Y 7 Rvrs

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.	
1. Set 7" CIBP @ 3450', Spot 40 Sx plug 3450'-3250', (Jalmat) WOC Tag	
2. Displace hole w/MLF, 9.5# Brine W/25# gel P/BBL	
3. Spot 60 Sx plug 3050'-2700' (9 5/8" Shoe) WOC Tag	
4. Spot 40 Sx plug 2550'-2350' (B-Salt)	
5. Perf 6 holes @ 1500', Sqz 75 Sx 1500'-1200' (T-Salt) WOC Tag	
6. Perf 6 holes @ 360', Sqz 125 Sx 360'-200' (13" Shoe) WOC Tag	
7. 10 Sx plug 10'-Surf. Install dry hole marker.	

THIS DOCUMENT IS A COPY OF THE ORIGINAL
FILED IN THE OFFICE OF THE SECRETARY OF
ENERGY, MINERALS AND NATURAL RESOURCES
STATE OF NEW MEXICO
DATE 2/7/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James T. Corbett TITLE FACILITY ENGR. DATE 2/7/01
Type or print name JAMES T. CORBETT Telephone No. 915 688-4438
(This space for State use)

APPROVED BY _____ TITLE _____ DATE FEB 07 2001
Conditions of approval, if any:

JC

dp