
Form C-108

OIL CONSERVATION COMMISSION



Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten day specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling oper-

ations, results of shooting well, results of test of cash even though the work was witnessed by an agent of and sworn to before a notary public. See additional	the Comn	nission. Report	s on mino:	operations nec	ed not be signed
Indicate nature	of repo	rt by checking b	elow:		
REPORT ON BEGINNING DRILLING OPERA-		REPORT ON REPAIRING WEL			.
REPORT ON RESULT OF SHOOTING OR CHEM- ICAL TREATMENT OF WELL			N PULLIN	G OR OTHERV	WISE
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON	I DEEPEN	IING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X				
	Kid	land, Texas		November 3	ւ, 1946
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO. Gentlemen: Following is a report on the work done and the resu	lts obtain	Place	eading note	ed above at the	Date
Humble Oil & Refining Company Company or Operator	J. L.	Lease	Wel	l No2	in the
MW/L of NE/L of Sec. 10)	T. 24-8	, R.	36 - E	, N. M. P. M.,
Cooper-Jal Field,		Lea			County,
The dates of this work were as follows:	Octobe	r 22 to Oct			17
Notice of intention to do the work was (see see su	ubmitte d	on Form C-102	on	ctober 7,	19 46
Shot 6 5/8" casing at 1870; and pull Shot 8 5/8" at 1000; 100; and 100; surface with 15 sacks cement. Inter Levelled location and placed regulat	rail rals b	ed to recoverus	er any 8	3 5/8". Pli	ugged hole at
Witnessed by Name		Comp	any		Title
Subscribed and sworn before me this 1st day of November 19 46 Use has Ferguson Notary Public		I hereby swear or affirm that the information given above is true and correct Name Division Chief Clerk Representing Humble Oil & Refining Company Company or Operator			
My commission expires 6-1-47			Day 941		
		Address	Box 160	00 - Nidla	and, Texas
Remarks: APPROVED		Address	J.	ey ya	And, Texas

entile of the parties of the careful of the control of the control

Commence Search All March Commence Commence

(x,y,y,z) = (x,y,y',z) + (x,y,z',z)

· And the state of the state of