

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEASE OR PULL BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Getty Oil Company

3. Address of Operator
P.O. Box 730 Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE West LINE, SECTION 12 TOWNSHIP 24S RANGE 36E N.M.P.M.

7. Unit Agreement Name

Myers Langlie Mattix Uni

8. Term of Lease Name

Myers Langlie Mattix Uni

9. Well No.

242

10. Field and Pool, or Wildcat

Langlie Mattix

15. Elevation (Show whether D.F., RT, GR, etc.)

3359' D.F.

12. County

Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPS. ☐
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER Recement casing ☒

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Rig up pulling unit, pull rods and pump.
- (2) Install BOP and pull tubing.
- (3) Set retrievable BP @ 3300' and test casing.
- (4) Run cement bond log to find top of cement.
- (5) Perforate 2 holes at top of cement.
- (6) Establish circulation down casing and out bradenhead.
- (7) Pump 50 barrels color dyed plug to determine cement volume.
- (8) Mix sufficient cement to circulate to surface.
- (9) Displace cement within 100 feet of perforations.
- (10) WOC 24 hours.
- (11) Drill out cement and test casing.
- (12) Pull BP.
- (13) Run tubing, rods and pump and put back to pumping.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Les Clemens

TITLE Area Superintendent

DATE 1-31-78

Orig. Signed by
Les Clemens
Oil & Gas

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 21 1978

OIL CONSERVATION COMM.
HOBBS, N. M.