

COPIES RECEIVED	
DISTRIBUTION	
DATE	
BY	
NO. G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Supervisor
District
Office

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH, OR FOR APPLICATION FOR PERMIT (FORM C-151) FOR SUCH PROPOSALS.

1. WELL TYPE ☐ OIL WELL ☐ GAS WELL ☐ OTHER	2. Name of Operator Zia Energy, Inc.	3. State of New Mexico
4. Address P.O. Box 603, Hobbs, NM 88240	5. Well No. 1	6. Date of Report Today
7. Section H 2310 North 330	8. Township East 13 24S	9. Range 30E
10. Elevation (Show whether DF, RT, GR, etc.) 3001' DF-3000' GR	11. Name of Engineer Lanette Mattix	12. Date 1st

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

REPAIR REMEDIAL WORK ☒	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
REPAIR AFTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	REPAIRING CASING ☐
COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

13. Describe in brief the operations (Clearly state all pertinent details, and give pertinent dates, including estimated time of starting and proposed work). SEE RULE 1103.

1. Rig up well servicing unit. Pull rods, pump & 2 3/8" tubing. Install BOP.
2. Run 2950' 2 7/8" tbg. Set pkr. in 5 1/2" csg.
3. Fracture treat existing perforation through 2 7/8" tbg. using 4,000 GA, 45,000 GG KclW & 80,000 # sand.
4. Pul 2 7/8" tbg. & pkr.
5. Rerun 2 3/8" tbg. with a 1 3/4" x 16' tubing pump barrel. Rerun rods with a 1 3/4" pump plunger.
6. Place well back on production to recover load water.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Engineer DATE 5/20/03

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR
CONDITIONS OF APPROVAL, IF ANY:

TITLE DATE MAY 31 1983