

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Cooper "B"
8. Well No. 3
9. Pool name or Wildcat Rhodes Tansil Yates 7-Rvrs

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Meridian Oil Inc.	
3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810	
4. Well Location Unit Letter <u>A</u> : <u>330</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>East</u> Line Section <u>14</u> Township <u>24S</u> Range <u>36E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3355' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mill and knock CIBP @ 3450' to bottom. RIH w/casing scraper to +/- 3450', set cmt retainer @ +/- 3425'. Squeeze open hole under retainer with 75 sx Cl. C cmt. Set a CIBP @ +/- 2975'. Set cmt plug from 2700' to 2975' (10 sx). Circ hole with 9 ppg gelled brine.

Set cement plug @ 1140' - 1260' (15 sx). Set a plug from surface to 360' (40 sx).

Cut off casing 3' below ground level and install P&A marker. Clear and restore location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Connie L. Malik TITLE Reg. Compliance Rep. DATE 3/31/92

TYPE OR PRINT NAME Connie L. Malik

TELEPHONE NO. 915-688-6898

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

THIS COMPLETION MUST BE NOTED 24 HOURS AFTER THE COMPLETION OF PLANNED OPERATIONS FOR THE CIBP TO BE APPROVED.

APR 03 '92

MERIDIAN OIL
COOPER B NO. 3
JALMAT FIELD
LEA COUNTY, NEW MEXICO

KLM 11/18/91

