

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. B 152436	
7. Unit Agreement Name ---	
8. Farm or Lease Name J. L. Isbell	
9. Well No. 4	
10. Field and Pool, or Wildcat Jalmat	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Worldwide Energy Corporation
3. Address of Operator 1700 Broadway, Suite 1600, Denver, Colorado 80290
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>24 S</u> RANGE <u>36 E</u> NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Free-point, cut & pull 7", 14# prod. csg at or above 3000'.
 - Place 40 sx cmt plug in 7" stub. Cmt. calculated to lap csg stub, 100' inside csg & 50' in open hole.
 - Place 55 sx cmt plug 1408'+ to 1258'+.
 - Place 37 sx cmt plug 150'+ to 50'+. Weld steel cap on 9-5/8" sfc csg.
 - Mark well location w/steel marker 4" in diameter, 4' high, set in concrete w/well name, number & location welded on surface of marker.
 - Restore location & clear out equipment.
- Proposed starting date: November 1, 1977.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

1. 100' PLUG FROM 3278 TO 3378

2. LOAD HOLE W/ 9.5# BRINE MUD AFTER 1ST CUT POINT

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jon N. Dull TITLE Production Engineer DATE 10/6/77

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Expires 4/11/78

RECEIVED

1912.7

U. S. ARMY COMM.
HOBBS, H. M.