

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Bureau of Geology, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. 30-025-09610
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Cooper Jal Unit
8. Well No. 237
9. Pool name or Wildcat Jalmat, Tansil, Y, 7 Rvrs

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Injector <input type="checkbox"/>	
2. Name of Operator Texaco Exploration & Production, Inc.	
3. Address of Operator P. O. Box 3109, Midland, Texas 79702	
4. Well Location Unit Letter <u>0</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>23</u> Township <u>24-S</u> Range <u>36-E</u> NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MI & RU Plugging Equipment. 2/22/01
2. Set 7" CIBP @ 3000'. 2/23/01
3. Spot 60 sx Class C CMT @ 3000', Tag Toc @ 2687'. 2/23/01
4. Cut 7" Csg @ 1990'. 2/27/01
5. Spot 50 Sx Class @ Cmt 2040 Tag @ 1935. 2/28/01
6. Spot 65 Sx Class @ Cmt 1300' Tag @ 1090'. 2/28/01
7. Circ Well w/ 115 Sx Class @ Cmt 350'-Surface. 2/28/01
8. Installed Dry Hole Marker. 2/28/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Poly Abalos TITLE VICE-PRESIDENT DATE 2/28/01

Type or print name POLY ABALOS Telephone No. \_\_\_\_\_  
(This space for State use)

APPROVED BY [Signature] TITLE Asst. Sec. DATE 6-14-01  
Conditions of approval, if any:

WZKZ

49