


NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

Sheet No. 2 of 2 Sheets

# MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.



Indicate nature of notice by checking below:

|  |  |  |            |
|--|--|--|------------|
| NOTICE OF INTENTION TO TEST CASING<br>SHUT-OFF |  | NOTICE OF INTENTION TO SHOOT OR<br>CHEMICALLY TREAT WELL |            |
| NOTICE OF INTENTION TO CHANGE PLANS            |  | NOTICE OF INTENTION TO PULL OR<br>OTHERWISE ALTER CASING |            |
| NOTICE OF INTENTION TO REPAIR WELL             |  |  |            |
| NOTICE OF INTENTION TO DEEPEN WELL             |  | NOTICE OF INTENTION TO PLUG WELL                         | <b>XXX</b> |

Odessa, Texas

Place

December 13, 1941

Date

OIL CONSERVATION COMMISSION,  
Santa Fe, New Mexico

Gentlemen:

Following is a notice of intention to do certain work as described below at the \_\_\_\_\_

**Phillips Petroleum Company** **C. D. Woolworth** Well No. **3** in **SW/4 NW/4**  
Company or Operator Lease  
of Sec. **23**, T. **24 S**, R. **36 E**, N. M. P. M., **Cooper** Field,  
**Lee** County.

## FULL DETAILS OF PROPOSED PLAN OF WORK

FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

Load hole with heavy mud. Run cement plug (20 sacks) from 3257' to 3357', T. D. (Perforations 3300' to 3350'). Shoot 7" casing, starting at 2700' and shooting upward at 100' intervals until casing is free. After pulling casing will refill hole with heavy mud. Will put in 75' cement bridge (30 sacks) from bottom 9-5/8" casing at 1390' to 1315'. Will start shooting 9-5/8" casing at 500' and shoot at 100' intervals upward until casing is free. After pulling 9-5/8" casing will fill hole with heavy mud to within approximately 10' of surface and complete plugging with a 10' cement cap and standard pipe marker.

DEC 17 1941

Approved \_\_\_\_\_, 19 \_\_\_\_\_  
except as follows:

**Phillips Petroleum Company**

Company or Operator

By *M. L. Atkinson*

Position **District Superintendent**

Send communications regarding well to

Name **M. L. Atkinson**

Address **Box 6666, Odessa, Texas**

OIL CONSERVATION COMMISSION,

By *John M. Kelly*

Title

**JOHN M. KELLY**  
**State Geologist**

Secretary, Oil Conservation Commission