

CCD - Hobbs

Form 3160-5
(June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 19935. Lease Designation and Serial No.
LC-030177

6. If Indian, Alaska or Tribal Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E&P Inc.

3. Address and Telephone No.

P.O. Box 730; Hobbs, New Mexico 88240

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter A 660 FNL & 660 FEL Sec 1 T -26S R36E

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Shepherd, C.W. "A" Federal #4

9. API Well No.

30-02509838

10. Field and Pool, or Exploratory Area

Jalmat Tansill Yates Seven River

11. County or Parish, State

Lea, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☐ Other☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of work completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

2/2: Notify BLM (Mr. Cortez)

2/5: MUD PU P&A Equipment RIN w/ TBG Tag CIBP @ 2792 Mix mud and pump mud Circulate hole Mix & pump 10 sx CL C cmt on top of CIBP @ 2792. Ld Jts TBG Mix & pump 15 sx CL C cmt 2592-2495 Ld 35 Jts 2 3/8 TBG Mix & pump 15 CL C cmt @ 1160-1060 Ld 36 Jts Dig out surface valve perf @ 507 ft get a rate pumped 55 bbl down 4 1/2 Press 100 PSI no return on 7 5/8 4 1/2 flowing back. Get on 7 5/8 side pumped 6 bbl loaded press up 2000 PSI shakedown

2/6: Talk on BLM Steve ok to pump 50 sx cmt Bullhead down 4 1/2 Displ to 400' WOC Tag Perf @ 350. Tag cmt 386'. Perf @ 350 Circulate cmt down 4 1/2 out 7 5/8 Fill 4 1/2 RD cut head off weld on cap and install dry hole marker. Clean Location. Well Plugged out 2/6.

Sent to BLM 2/15/96

Sent copy to NMOCED

MCD

14. I hereby certify that the foregoing is true and correct

Signed

Title P&A Supervisor

Date 2/6/96

(This space for Federal or State office use)

Approved by
Conditions of approval, if any:

Title

Petroleum Engineer

Date

2/16/97

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See instruction on Reverse Side

JC

djt