

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER-

Name of Operator

Chevron U.S.A. Inc.

Address of Operator

P.O. Box 670 Hobbs, NM 88240

Location of Well

UNIT LETTER H 1980 FEET FROM THE North LINE AND 330 FEET FROM
THE East LINE, SECTION 12 TOWNSHIP 26S RANGE 36E N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name

Vinson Ramsay (NCT-A)

9. Well No.

2

10. Field and Pool, or WHDCM

Scarborough Yates, 7Rive

15. Elevation (Show whether DF, RT, GR, etc.)

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐
PERMANENTLY ABANDON ☐
OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed 9-14-88 thru 9-15-88

POOH w/production equipment. Set CIBP at 2716-18. Cap w/35' cmt. Perf at 1150'.
Disp hole w/ abandonment mud. Establish circulation, pmp 300sx Class C. Displace
w/water. Dig out cellar. Cut off WH. Weld plate on 8 5/8". Install Dry Hole
Marker. Clean location. Well P&A'd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

L. K. Elmido f/ M. E. Arima Staff Drilling Engineer

DATE Sept. 20, 1988

R. A. Smith OIL & GAS INSPECTOR

CONDITIONS OF APPROVAL, IF ANY:

DATE 10/7/1988