	-				
NO. OF COPIES RECEIVED		Form C - Superse			
DISTRIBUTION		•	nd C-103		
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effectiv	e 1-1-65		
FILE					
U.S.G.S.			Type of Leas		
LAND OFFICE		State		Fee	X
OPERATOR		5. State Oil	& Gas Lease	No.	
(DO NOT USE THIS FORM FOR	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT			(M
USE "APPLIC	ATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agre	eement Name	7777.	1111
OIL GAS WELL		Penrose	"A"	Uni	
2. Name of Operator	OTHER- Water Injection	8, Farm or J	Lease Name		
Skelly Oil Company		Skelly	Penrose	"A"	Unit
3. Address of Operator		9. Well No.			
P. O. Box 1351, Mid	land. Texas 79701	38			
4. Location of Well		10, Field an	nd Pool, or Wi	ldcat	
UNIT LETTERN	740 FEET FROM THE South LINE AND 2000 FEET FROM	Langli	e-Mattix		
			<u>IIIII</u>	\overline{III}	TTTI,
THE West LINE, SEC	TION3TOWNSHIP238RANGE37ENMPM.			////	1111.
· · · · · · · · · · · · · · · · · · ·	15. Elevation (Show whether DF, RT, GR, etc.)			$\Pi \Pi$	1111
	12. County		\overline{M}	1111	
	3297' DF	Lea		\overline{III}	7111.
^{16.} Chec	k Appropriate Box To Indicate Nature of Notice, Report or Otl	her Data			
NOTICE OF	INTENTION TO: SUBSEQUENT	REPORT	OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	,	ALTERING CASI	NG	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS,	1	PLUG AND ABAN	DONMEN	NT 🗌
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	t nowfor	ata 14ma	-	NV -1
	OTHER Install, cement	a perror	are True		X
OTHER					

- 1) Moved in pulling unit 4-16-73. Pulled tubing and packer.
- 2) Cleaned out to 3630' TD.
- 3) Ran 10 jts. (333') of 5" OD 13# K55 Condition "A" casing liner. Bottom of liner set at 3629' and top of liner hanger set at 3277'. Treated formation with 1000 gallons of 5% MCA acid and 1000 gallons of water containing 5 gallons of Morflo 2.
- 4) Cemented 5" OD liner with 800 sacks of 50-50 Pozmix cement, 2% gel, 1% CFR-2, 3# of potassium chloride. Displaced 700 sacks behind liner. Set packer and squeezed 100 sacks into formation. WOC 16 hours.
- 5) Cleaned out to top of liner at 3277'.
- 6) Ran tubing and set packer at 3245'. Tested to 3000# for 15 minutes; held okay. Pulled tubing and packer.
- 7) Drilled out cement out of 5" OD liner to 3628' PBTD.
- 8) Ran Gamma Ray-Neutron Log 2700-3620'.
- 9) Perforated 5" OD liner with one .50" shot at each of the following places: 3520' 3533', 3543', 3557', 3568', 3591', 3603', 3615', and 3621'.
- 10) Treated perforations 3520-3621' with 750 gallons of 15% NE acid, using 18 ball sealers.
- 11) Ran 107 jts. (3321') 2-3/8" OD cement lined tubing.

NED (C. 300.00)	0.0.00	D. R. Crow	Lead Clerk	May 29, 1973
<u></u>		in the second		
ROVED BY			TITLE	DATE