

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Skelly Oil Company	8. Farm or Lease Name R. R. Sims
3. Address of Operator P. O. Box 1351, Midland, Texas 79701	9. Well No. 7
4. Location of Well UNIT LETTER K 2200 FEET FROM THE South LINE AND 2200 FEET FROM THE West LINE, SECTION 3 TOWNSHIP 23S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Blinebry, West
15. Elevation (Show whether DF, RT, GR, etc.) 3307' DF	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER Plug & abandon the Blinebry zone <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well bore will be taken into Skelly Oil Company's Penrose "A" Unit as Well No. 62. The Blinebry zone has been plugged and abandoned as follows:

- 1) Moved in pulling unit 3-8-73. Pulled tubing and packer.
- 2) Spotted 35' cement plug 5713-5748'.
- 3) Set cast iron bridge plug at 5517' and capped with 35' of cement 5482-5517'.
- 4) Spotted 100' cement plug 5140-5240'.
- 5) Shot off 5-1/2" OD casing at 3855'.
- 6) Recovered 3855' of 5-1/2" OD 17# casing.
- 7) Spotted 337' cement plug 3720-4057' across top of 5-1/2" OD casing cut off point and across 9-5/8" OD casing shoe.

All intervals below 4057' not cemented were filled with 10# mud.

The 13-3/8" OD 44.5# casing set at 192', and 9-5/8" OD 36# casing were left in the hole. Also, 5-1/2" OD 17# casing from 3855' to 6650' was left in the bottom of the hole.

The Blinebry zone was plugged and abandoned 3-17-73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Signed) D. R. Crow **D. R. Crow** TITLE Lead Clerk DATE March 20, 1973

APPROVED BY Joe D. Ramey **Joe D. Ramey** TITLE Dist. 1, Supv. DATE

CONDITIONS OF APPROVAL, IF ANY: