

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
03 025 10613

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Texaco Exploration and Production Inc.

3. Address of Operator  
P. O. Box 730 Hobbs, NM 88240

4. Well Location  
Unit Letter C : 660 Feet From The NORTH Line and 1980 Feet From The WEST Line  
County

Section 4 Township 23S Range 37E NMPM LEA

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3304' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-14-92 DA&S Abandonment report on reverse side:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L.W. Johnson TITLE Engr Asst DATE 11/02/92

TYPE OR PRINT NAME L.W. Johnson TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY Lyle F. Turnacliff TITLE OIL & GAS INSPECTOR DATE DEC 28 '92  
CONDITIONS OF APPROVAL, IF ANY:

# DA&S OIL WELL SERVICING

INCORPORATED

TEXACO  
PENROSE "A" - #18

- 10/13/92 - MOVE IN, RIG UP, INSTALL B.O.P., RUN CEMENT BONDLOG FROM 2390' TO SURFACE, GOOD CEMENT FROM 920'-870', SOME CEMENT UP TO 200' FROM SURFACE.  
RUN TUBING IN HOLE, TAG CEMENT RETAINER AT 2390', CIRCULATE MUD, SPOT 6 SACKS OF CEMENT FROM 2390'-2354', PULL TUBING TO 1300', SPOT 25 SACKS OF CEMENT, PULL TUBING, SHUT DOWN.
- 10/14/92 - RUN TUBING, TAG CEMENT AT 1149', PLUG FROM 1300'-1149', PULL TUBING OUT, PERFORATE WELL AT 200' FROM SURFACE, CIRCULATE WELL, PUMP 150 SACKS OF CEMENT DOWN 7" CASING TO PERFORATION AT 200', UP 16" TO SURFACE, CUT OFF WELLHEAD, INSTALL MARKER, FILL COLLAR WITH CEMENT, RIG DOWN, MOVE OFF.

9.5 p.p.g. SALT GEL MUD  
CLASS "C" CEMENT

RECEIVED

NOV 0 8 1992

OCD HOBBS OIL

505-392-6591

P.O. BOX 2545

HOBBS, NEW MEXICO 88241

#### LOCATIONS

HOBBS, NEW MEXICO (505) 392-6591  
ANDREWS, TEXAS (915) 523-4420

EUNICE, NEW MEXICO (505) 394-2557  
MIDLAND, TEXAS (915) 685-8555