	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State Fee 5. State Oil & Gas Lease No. 7. Unit Agreement Name Kelly Penrose "A" Unit 8. Farm of Lease Name
U.S.G.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT	State Fee State Oil & Gas Lease No.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. OIL GAS WELL OTHER- 2. Name of Operator SKELLY OIL COPPANY 3. Address of Operator P. O. Box 730 - Hobbs, New Maxico 88240 4. Location of Well UNIT LETTER	Skelly Penrose"A" Unit
well well other- 2. Name of Operator SKELLY OIL COMPANY 3. Address of Operator P. O. Box 730 - Hobbs, New Maxico 88240 4. Location of Well UNIT LETTER <u>"T" 1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET	
4. Location of Well UNIT LETTER	9. Well No.
THE West LINE, SECTION 4 TOWNSHIP 238 RANGE 378	19 10. Field and Pool, or Wildcat Langlie Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3331 DF	MPM.
16. Check Appropriate Box To Indicate Nature of Notice, Report o NOTICE OF INTENTION TO: SUBSEQU	Other Data
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	ALTERING CASING

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

<u>HOTE</u>: During the attempt to convert this well to injection service, the tubing parted, resulting in the loss of tubing and a tension type packer in the hole. Most of the tubing was recovered, but attempts to recover the packer were unsuccessful and all indications are that the 7"CD casing is parted or collapsed above the packer at about 2280' to 2300'. Attempts to mill over the packer resulted in the workover tools leaving the casing in the interval 2280-2300' (by Schlumberger Collar Log). A new hole was washed and drilled to 2690' alongside the existing casing string. Bue to this, the tubing was run inside 7"CD casing to about 2280', then outside to perforate 7"CD casing and spot cement plugs to plug and abandon this well.

Moved in and rigged up Workover Unit. Ran 2-7/8"CD tubing open-ended to 2615' outside 7"CD casing, unable to ge below 2615'. Raised tubing to 2475'. Perforated 7"CD casing down 2-7/8" CD tubing 2493-2503' with 4 shots per feet, no less of fluid. Raised tubing to 2445' and perforated 7"CD casing down 2-7/8"CD tubing 2455-2465' with 4 shots per feet and no less of fluid. Lowered tubing to 2513', circulated hole clean and spotted 150 sacks cement. Pulled tubing.

	(Cont	inued on next page)				
18. I hereby certify that the information above is true and comple	ete to the	best of my knowledge and belief.				
(ORIGINAL) V. E. Fletcher	TITLE	District Superintendent	. DATE	June	3,	1968
APPROVED BY JOMM W. Runyan CONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE			
CONDITIONS OF APPROVAL, IF ANY:						