

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 - 025 - 10623
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name SKELLY PENROSE A UNIT
2. Name of Operator Texaco Exploration and Production Inc.	8. Well No. 33
3. Address of Operator P. O. Box 730 Hobbs, NM 88240	9. Pool name or Wildcat LANGLIE MATTIX 7R QN GB
4. Well Location Unit Letter <u>M</u> : <u>500</u> Feet From The <u>SOUTH</u> Line and <u>990</u> Feet From The <u>WEST</u> Line Section <u>4</u> Township <u>23-S</u> Range <u>37-E</u> NMPM LEA	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3328' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: CASING INTEGRITY TEST <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-20-92:

1. Pull rods and tubing, lay down.
2. Set CIBP at 3476', dump 50' cement on top.
3. Test 5-1/2" casing to 500 psi for 30 minutes. Held OK.
4. Request TA status.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert McNaughton TITLE Production Engineer DATE 6-4-92
TYPE OR PRINT NAME Robert McNaughton TELEPHONE NO. 397-0428

(This space for State Use)

APPROVED BY JOSEPH STAXOM
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:


This Approval of Temporary
Abandonment Expires 6-4-93

JUN 08 '92

RECEIVED

JUN 04 1992

OCD HOBBS OFFICE



RECEIVED
JUN 04 1992
OCD HOBBS OFFICE