

Sumbit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling opera-tions, results of shooting well, results of test of casing shut off, result of plugging of well, and other important opera-tions, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission. 17

Indicate nature of report by checking below.

TIONS	I REFORT	ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEM- ICAL TREATMENT OF WELL		ON PULLING OR OTHERWISI RING CASING	E
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT	ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		
	April 1, 1949		
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO. Gentlemen:	Date	Plac	e
Following is a report on the work done and the resu			
<u>Ralph Lowe</u> Company or Operator	E. F. King Lease	Well No2	in the
SE NEof Sec	r 00.0	, <u>R</u> 37-E,	N. M. P. M.,
Penrose-Skelly Field,	,	Lea	County.
The dates of this work were as follows:	March 31, 1949	······································	County.
Notice of intention to do the work was (RECEXCED)			19 49
DETAILED ACCOUNT OF T.D. 3805' - Pulled 8 5/8" and 7" Ca and dumped 10 sax coment. Same proc 10 sax @ 325'. 10 3/4" Csg. comente set at surface. Cellar & pits level	sing. Filled wi edure for plugs d @ 325' with 15	th mud to 3600'. Sed 1 @ 2550', 1330'. 15 sax	plug 760.
T.D. 3805' - Pulled 8 5/8" and 7" Ca and dumped 10 sax coment. Same proc 10 sax @ 325'. 10 3/4" Csg. comente set at surface. Cellar & pits level	sing. Filled wi edure for plugs ed @ 325' with 15 led.	th mud to 3600'. Sed 1 @ 2550', 1330'. 15 sax	plug 760.
T.D. 3805' - Pulled 8 5/8" and 7" Ca and dumped 10 sax coment. Same proc 10 sax © 325'. 10 3/4" Csg. comente set at surface. Cellar & pits level Witnessed by	sing. Filled wi edure for plugs ed @ 325' with 15 led. Ralph Lowe	th mud to 3600'. Sed © 2550', 1330', 15 sax 50 sax cement. Regulat: Tool;	plug 760, ion markes
T.D. 3805' - Pulled 8 5/8" and 7" Ca and dumped 10 sax coment. Same proc 10 sax © 325'. 10 3/4" Csg. comente set at surface. Cellar & pits level Bill Scott	sing. Filled wi edure for plugs ed @ 325' with 15 led. Ralph Lowe	th mud to 3600'. Sed 1 @ 2550', 1330', 15 sax 50 sax cement. Regulat:	plug 760, ion mark er s
T.D. 3805' - Pulled 8 5/8" and 7" Ca and dumped 10 sax coment. Same proc 10 sax © 325'. 10 3/4" Csg. cemente set at surface. Cellar & pits level Witnessed by	Ralph Lowe I hereby swear is true and cor	Tool mpany or affirm that the information	plug 760, ion ma rkes usher Title
T.D. 3805' - Pulled 8 5/8" and 7" Ga and dumped 10 sax cement. Same proc 10 sax © 325'. 10 3/4" Csg. cemente set at surface. Cellar & pits level Witnessed by	Ralph Lowe I hereby swear is true and cor	Tool mpany or affirm that the information rect. Markow Multell	plug 760, ion ma rke ma rke Title
T.D. 3805' - Pulled 8 5/8" and 7" Ca and dumped 10 sax coment. Same proc 10 sax © 325'. 10 3/4" Csg. cemente set at surface. Cellar & pits level Witnessed by	Ralph Lowe I hereby swear is true and cor Position	Tool mpany or affirm that the information rect. Markow Multell	plug 760, ion ma rkes usher Title
T.D. 3805' - Pulled 8 5/8" and 7" Ga and dumped 10 sax coment. Same proc 10 sax © 325'. 10 3/4" Csg. cemente set at surface. Cellar & pits level Witnessed by Witnessed by Bill Scott Name Subscribed and sworn before me this day ofApril	Ralph Lowe I hereby swear is true and cor Position	Tool; mpany or affirm that the information meet. Me.Mublell Agent RALPH LOWE Company or Operator	plug 760, ion ma rkes usher Title