Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

CONDITIONS OF APPROVAL, IF ANY:

DISTRICT I	III. CONSERVATION	J DIVICION -			
P.O. Box 1980, Hobbs, NM 88240			WELL API NO. 34262		
DISTRICT II	STRICT II Santa Fe New Mexico 87504-2088		30-025- 10643 10643 Kz		
P.O. Drawer DD, Artesia, NM 88210		7504 2000	5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			STATE 6. State Oil & Gas Lease No.	FEE X	
1000 1000 1000, 111200, 1471 07410			o. State Oil & Gas Lease No.		
SUNDRY NOTICE	S AND REPORTS ON WELL	s			
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN O	R PLUG BACK TO A	7. Lease Name or Unit Agreement	Nome	
DIFFERENT RESERVO	IR. USE "APPLICATION FOR PERM) FOR SUCH PROPOSALS.)	AIT"	7. Load valle of Out Agreement	Name	
1. Type of Well:	TOTT GOOTT HOT GOALS.)		Skelly Penrose B	Unit	
OIL GAS OTHER WIW			swerry remrose b		
2. Name of Operator			8. Well No.		
Sirgo Operating, Inc.			32		
3. Address of Operator			9. Pool name or Wildcat		
P.O. Box 3531, Midlar 4. Well Location	id, Texas 79702		Langlie Mattix SR	-Q-GB	
Unit Letter J : 1980	P.P. m. South	1000			
Unit Letter : 1900	reet From The South	Line and1980	Feet From The East	Line	
Section 5	Township 23S Range	37E N	ирм Lea		
	10. Elevation (Show whether DF	, RKB, RT, GR, etc.)	Y//////.	County	
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	3335 GR 3345		<i>\\\\\\\\</i>		
11. Check App	ropriate Box to Indicate Na	ture of Notice, Rep	ort, or Other Data		
NOTICE OF INTEN		_	EQUENT REPORT O	F.	
DEDECOM DEMEDIAL MODIC	51.15			_	
PERFORM REMEDIAL WORK	PLUG AND ABANDON P	REMEDIAL WORK	X ALTERING CA	SING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING C	PNS. PLUG AND AB	ANDONMENT .	
PULL OR ALTER CASING		ACINO TECT AND OTHE	[]		
_		ASING TEST AND CEMI	ENT JOB []		
OTHER:	U °	OTHER:			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and g	ive pertinent dates, including	estimated date of starting any pro	noved	
work) SEE RULE 1103.	_	•	and the same of th	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
2-11-91 RU PU. POOH w/t	la calamanta				
	bg & pkr. Tag 35' of	till. POOH & SD			
	c bailer & clean out 1/8" tbg. Set pkr @ 342	20 ID. PUUH W/D	aller. RIH W/AD-I p	kr	
acid. SI 30 min.	Flow well back & swal	b back 60 bbls.	The dry SD	.500 gal	
2-13-91 Swab well dry. U	nset pkr. POOH.RIH w	/pkr & prod str	ing. Circ pkr fluid	l. Set pkr.	
Not holding. POO	H. Try to test in hole	e . Tbg bad, SD	_		
2-14-91 RIH w tbg from wo 2-15-91 RD.	ell #52 & hydrotest in	n hole. Circ pk	r fluid & set pkr @	3456'. SD.	
2-13-91 KD.					
I hereby certify that the information above is true and co	implete to the best of my knowledge and belie	f			
SIGNATURE Donnis / Thu	ater me	Production Tec	chnician DATE 2	- 22 - 91	
			DATE		
TYPEOR PRINTNAME Bonnie Atwate	÷r		TELEPHONE NO	<u>0.915/685-0</u> 878	
(This space for State Use)	. 2.7.27 2. 3.3 %.				
	en programme in the state of th			FED A V ID:	
APPROVED BY	TITLE		DATE	States Full	
			2015		