

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate  
Other Instructions  
Reverse Side

August 31, 1988  
LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED  
SEP 23 9 05 AM '89

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Conoco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 460 - Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1650' FSL & 1650' FEL Unit 1

14. PERMIT NO.

30-025-10664

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3362' DF

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Stevens B

9. WELL NO.

#12

10. FIELD AND POOL, OR WILDCAT

Langley Mattix 7krs. Queen

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 7, T235, R37E

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to P+A this well according to the following procedure:

1. MIRR. POOH w/production equip. Kill well. ND wellhead. Nu BOP
2. Set ret. @ 2500'. String out of ret. and circ. hole w/60 Bbls mud. Pump 70.5 sx cmt to fill 4" liner & 5 1/2" csq from 3668 to 2500'. Spot remaining 5.5 sx of cmt on top of ret. (TOC @ 2450')
3. Spot cmt plug from 1270' to 1160' w/11.5 sx cmt.
4. Perf. 5 1/2" prod. csq @ 240' w/2 JSPP. Establish circ. up annulus. Pump 55 sx cmt to fill 7 5/8" x 5 1/2" annulus & set surf. plug.
5. ND BOP, cut off csq at base of cellar. Fill csq strings to surface w/cmt. Erect P+A marker.

\* RESTORE LOCATION.

\* NOTIFY BLM---

18. I hereby certify that the foregoing is true and correct

SIGNED W. W. Baker W. W. Baker

TITLE Administrative Supervisor

DATE Sept. 21, 1989

(This space for Federal or State office use)

APPROVED BY Adam Salameh

TITLE

DATE 10/3/89

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side