

Submit 3 Copies
to Appropriate
District Office
District I
P.O. Box 1980, Hobbs, NM 88240
District II
P.O. Drawer DD, Artesia, NM 88210
District III
1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

WELL API NO.	30 - 025 - 10669
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit agreement Name SKELLY PENROSE B UNIT
2. Name of Operator OXY USA INC.	8. Well No. 48
3. Address of Operator P.O. Box 50250 Midland, TX 79710	9. Pool name or Wildcat LANGLIE MATTIX 7 RVR Q-GB
4. Well Location Unit Letter <u>E</u> : <u>1,980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>8</u> Township <u>23 S</u> Range <u>37 E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,347	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TEMPORARILY ABANDON <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3740' PBTD - 3687' PERFS - 3560' - 3684'

MIRU PU 6/14/93, NDWH, NUBOP, POOH W/ 1 JT TBG SUB, RIH & TAG @ 3668', CO TO 3687'. RIH W/ PKR & TBG & SET @ 3514, TEST CSG TO 500# - HELD OK, POOH. RIH W/ CIBP & SET @ 3514', CIRC HOLE W/ CORR INHIB, TEST CSG TO 500# - 30 MIN, POOH W/ TBG, NDBOP, NUWH W/ 1JT TBG & VALVE, RDPU 6/17/93. WELL IS TA'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 06 24 93
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUL 06 1993


CONDITIONS OF APPROVAL, IF ANY:

Approval of Temporary
Abandonment Expires 7-1-98

RECEIVED

JUN 25 1993

CLERK HOBBS
OFFICE



7-17-93
CHAPARRAL SERV.
Arthur Luni
Penrose #48
OXY USA

RECEIVED

JUN 25 1993

JOE HOBBS
OFFICE