

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Oil and Gas
Conservation
Division

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.


☒ OIL ☐ GAS WELL ☐ OTHER	1. Name of Operator Skelly Oil Company 2. Address of Operator P. O. Box 1351, Midland, Texas 79701 3. Location of Well UNIT LETTER H , 1650 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 23S RANGE 37E 15. Elevation (Show whether DF, RT, GR, etc.) 3320' DF	4. Name of Well Skelly Penrose "B" Unit Skelly Penrose "B" Unit 50 Langlie-Mattix Lea
--	---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☒ CHANGE PLANS ☐ OTHER ☐	REMEDIAL WORK ☐ COMMENCE DRILLING OPERATIONS ☐ CASING TEST AND CEMENT ☐ OTHER ☐	ALTERED PLAN ☐ IS NOT A PLUG BACK ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data for each proposed operation) SEE RULE 1103.

- 1) Move in workover rig.
- 2) Spot cement plug 3358-3458'.
- 3) Shoot off 5-1/2" OD casing at 2200' and pull.
- 4) Spot cement plug 2150-2300'.
- 5) Spot cement plug 1200-1300'.
- 6) Spot cement plug surface to 60'.
- 7) Install dry hole marker.

Note: All intervals not cemented will be filled with 10.2# mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge.	
(Signed) D. R. Crow SIGNED D. R. Crow TITLE Lead Clerk	2-3-75
APPROVED BY  CONDITIONS OF APPROVAL, IF ANY:	SUPERVISOR DISTRICT I