NO. OF COPIES RECEIVED					Form C-103		
DISTRIBUTION					Supersedes O	Old	
SANTA FE		NEW MEXICO OIL MORSERVATION COMMISSION			C-102 and C-		
FILE	<del>                                     </del>	NEW WEXICO OIL BONSE	KVATION COMMISSION		Effective 1-1-	-65	
	<del>                                     </del>	11 21	3 11 38 AM '67	l e	a. Indicate Type	o of Loggo	
U.S.G.S.		MAR L	)    30 mi vi	ľ		Fee.	
LAND OFFICE				<u> </u>	State		
OPERATOR	<u> </u>			5	5. State Oil & Go	is Lease No.	
					•••	**	
	SUNDRY NOTICE	S AND REPORTS ON	WELLS	- 1			
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)							
1.				7	7. Unit Agreement Name		
OIL GAS WELL	OTHER-				Skelly Per	nrose "B" Unit	
2. Name of Operator			•		. Farm or Lease		
Skelly	Oil Company			l	••	-	
3. Address of Operator				9	Well No.		
P.O.	Box 730, Hobbs	. New Mexico			59		
4. Location of Well				1	0. Field and Po		
•	490	# amela	Manuala 990		Langlie Mattix		
UNIT LETTER	,FE	ET FROM THE South	LINE AND	FEET FROM	- rungere	Mactal (1)	
	_		A				
THE BEST L	INE, SECTION	TOWNSHIP	RANGE 37K	NMPM.			
					7777777	7//////////////////////////////////////	
	//////////////////////////////////////	. Elevation (Show whether I	· · · · · · · · · · · · · · · · · · ·	1	2. County		
		3336' D	<u> </u>		Les	<u> </u>	
16.	Check Appropriat	e Box To Indicate Na	ature of Notice. Repo	ort or Other	r Data		
NOTIC	CE OF INTENTION				REPORT OF:	:	
				• •			
PERFORM REMEDIAL WORK	7	PLUG AND ABANDON	REMEDIAL WORK	T	A1.755	RING CASING	
	าี่	TEGG AND ABANDON []				F===	
TEMPORARILY ABANDON	╡		COMMENCE DRILLING OPNS.		PLUG A	AND ABANDONMENT	
PULL OR ALTER CASING	_	CHANGE PLANS	CASING TEST AND CEMENT JO				
			OTHER				
OTHER							
17. Describe Proposed or Co	mnleted Operations (Cle	arly state all pertinent deta	ils and aive pertinent dates	including es	timated date of	starting any proposed	
work) SEE RULE 1103.	impleted Operations (ore	arry state are pertinent deta	is, and give periment dates	, merating es	timatea date of	starting any proposed	
1. Moved in and	rieged up work	cover unit.					
2. Rep cmershot							
		·					
3. Cleaned out							
4. Ren Germe Rey							
		stalled pumping e	darbwesse.				
6. Pumped and to	ested for sever	rai days.					
7. Well returned	d to production	s status March 27	, 1967.				
	-		-				
18. I hereby certify that the i		and complete to the best of	my knowledge and belief.				
ORIGIN	IAL) V. B. Flat	cher					
\ SIGNE	V. E. Flet	Mie	trict Superinten	dent	Mar.	rch 28, 1967	
SIGNED		TITLE #44			DATE		
	,	,					

CONDITIONS OF APPROVAL, TP ANY: